



VOLVO PARTS
1 040 10841

| Sida Page | Grupp Group | Bakaxel,upphängning | Rear axle,mountings | Illustration | 1550 | | | | | |
|-----------|----------------|--|--|------------------|--------------------|-------------------------------|------------------------------|----------------|--|--|
| 116 | 4 | 142 CH 112400-,144 CH 138700- 145 CH 30900- | 142 CH 112400-,144 CH 138700- 145 CH 30900- | 10841 1979-11 | | | | | | |
| Pos. Fig. | Antal/Quantity | | | | Artikel nr Part No | Benämning | Description | Sats Kit P S R | Anmärkning Notes | |
| 1 | 1 | - | - | - | 255626-4 | Bakaxel | Rear axle | 8 | 30, 45) BXL UTV 4.10/1 ERS AV 255802-1. | 1010 |
| | 1 | - | - | - | 255697-5 | Bakaxel | Rear axle | 8 | 42) BXL UTV 4.10/1 ERS AV 255802-1. | 1011 1020 |
| | 1 | - | - | - | 255693-4 | Bakaxel | Rear axle | 8 | BXL UTV 4.10/1 142, 144 B20E. 145 B20E, F ERS AV 1ST 255802-1, 1 ST 384720-9 | 1021 1030 1031 1040 1050 1060 |
| | 1 | - | - | - | 255627-2 | Bakaxel | Rear axle | 8 | 30, 45) BXL UTV 4.30/1 ERS AV 255803-9 | 1070 1071 |
| | 1 | - | - | - | 255698-3 | Bakaxel | Rear axle | 8 | 42) BXL UTV 4.30/1 ERS AV 255803-9 | 30 1081 |
| | 1 | - | - | - | 255694-2 | Bakaxel | Rear axle | 8 | BXL UTV 4.30/1 142, 144 B20E 145 B20E, F ERS AV 1ST 255803-9 1 ST 384720-9 | 1090 1091 1100 1110 1130 |
| | - | - | - | - | | •Det se sida 126, 2-K07 | •Comps page 126, 2-K07 | | | 1140 |
| x 2 | 2 | - | - | - | 384705-0 | Drivaxel | Drive shaft | | | 1150 |
| x 3 | 2 | - | - | - | 383168-2 | Distansring | Spacer ring | | (384707) | 1160 |
| 4 | 2 | - | - | - | 384728-2 | Rullager | Roller bearing | | | 1170 |
| 5 | 2 | - | - | - | 384710-0 | Tätningarring | Seal ring | | | 1180 |
| 6 | 2 | - | - | - | 384706-8 | Tryckplåt | Pressure plate | | | 1190 |
| 7 | 8 | - | - | - | 944209-6 | Flänsskruv | Flange screw | | (940115) | 1200 |
| 8 | 8 | - | - | - | 942336-9 | Låsbricka | Lock washer | | TID.UTF. | 1210 |
| 9 | 10 | - | - | - | 676338-7 | Hjulbult | Wheel stud | | STDD | 1220 |
| | 10 | - | - | - | 676364-3 | Hjulbult | Wheel stud | | ÖD | 1230 |
| 9a | - | - | - | - | | Mutter | Nut | | SE GRUPP 6 | 1240 |
| x 10 | 1 | - | - | - | 662014-0 | Urluftningsnippel | Air venting nipple | | | 1250 |
| x 11 | 1 | - | - | - | 946763-0 | Plastslang | Plastic hose | | (943185) | 1260 |
| 12 | 1 | - | - | - | 96443-7 | Gummibussning | Rubber bushing | | | 1270 |
| 13 | 2 | - | - | - | 679451-5 | Bärring | Support arm | | 30) | 1280 |
| | 2 | - | - | - | 686706-3 | Bärring | Support arm | | 31) EXCL.B20E | 1290 |
| | 2 | - | - | - | 686729-5 | Bärring | Support arm | | 31) B20E | 1300 |
| 14 | 2 | - | - | - | 676914-5 | •Bussning | •Bushing | | 30,31) EXCL.B20EE | 1310 |
| | 2 | - | - | - | 678887-1 | •Bussning | •Bushing | | 31) B20E | 1320 |
| 15 | 2 | - | - | - | 941858-3 | Skruv | Bolt | | | 1330 |
| 16 | 2 | - | - | - | 950377-2 | Mutter | Nut | | | 1340 |
| 17 | 2 | - | - | - | 675778-5 | Bussning | Bushing | | | 1350 |
| 18 | 2 | - | - | - | 955744-8 | Skruv | Bolt | | | 1360 |
| 19 | 2 | - | - | - | 950378-0 | Mutter | Nut | | | 1370 |
| 20 | 2 | - | - | - | 672616-0 | Bärstag | Support stay | | 27) | 1380 |
| | 2 | - | - | - | 686805-3 | Bärstag | Support stay | | 28) | 1390 |
| | 2 | - | - | - | 686257-7 | Bärstag | Support stay | | 31) | 1400 |
| 21 | 4 | - | - | - | 678790-7 | •Bussning | •Bushing | | | 1410 |
| 22 | 2 | - | - | - | 675850-2 | Konsol | Bracket | | | 1420 |
| 23 | 2 | - | - | - | 943885-4 | Flänsskruv | Flanged screw | | (955559) | |

27. 142 CH -125025 excl. 123079-123500, 123691-124854. 144 CH -148941 excl. 147286-147311, 147374-147510, 147867-148755. 145 CH -36061 excl. 33950-34086, 34141-34694, 34790-35409, 354442-36031.
28. 142 CH 123079-123500, 123691-124854, 125026-178959. 144 CH 147286-147311, 147374-147510, 147867-148755, 148942-194139, 194149-194301. 145 CH 33950-34086, 34141-34694, 34790-35409, 35442-36031, 36062-61599, 61610-61624.
30. 142 CH 112400-178959. 144 CH 138700-194139, 194149-194391. 145 CH 61610-61624.
31. 142 CH 178960-. 144 CH 194140-194148, 194302-. 145 CH 61600-61609, 61625-.
42. 142 B20A, B, D, F CH 178960-. 144 B20A, B, D, F CH 194302- incl 194140-194148. 145 B20A, B, D.
45. Ersättes på följande CH nr även av 2 st 672616-0. Replaced on following chassis nos. also by: 2 pos. 672616-0.
Est remplacé sur les numéros de châssis suivants, même par 2 pièces 672616-0. Wird bei folgenden Fahrgestellnummern auch durch 2 St 672616-0 ersetzt. Se substituye en los siguientes números de chasis por 2 unidades 672616-0. 142 CH 123079-123500, 123691-124854, 125026-178959. 144 CH 147286-147311, 147374-147510, 147867-148755, 148942-194139, 194149-194301. 145 CH 33950-34086, 34141-34694, 34790-35409, 35442-36031, 36062-61599, 61610-61624.

| Sida Page | Grupp Group | Bakaxel,upphängning 142 CH 112400-,144 CH 138700- 145 CH 30900- | Rear axle,mountings 142 CH 112400-,144 CH 138700- 145 CH 30900- | Illustration 10841 1979-11 | 1550 | | | | | |
|--------------|----------------|---|---|----------------------------------|---------------------------------|-------------------------------------|-------------|------------------|--|------|
| Pos. Fig. | Antal/Quantity | | | Artikel nr Part No | Benämning | Description | Sats Kit | B P S R | Anmärkning Notes | |
| 24 | 2 | - | - | 955568-1 | Skruv | Screw | | | 32) | 1430 |
| | 2 | - | - | 955567-3 | Skruv | Screw | | | 33) | 1440 |
| 25 | 4 | - | - | 940280-1 | Fjädrande bricka | Resilient washer | | | | 1450 |
| 26 | 2 | - | - | 960145-1 | Bricka | Washer | | | 32) | 1460 |
| 27 | 2 | - | - | 955569-9 | Skruv | Bolt | | | | 1470 |
| 28 | 2 | - | - | 950356-6 | Mutter | Nut | | | | 1480 |
| 29 | 1 | - | - | 677284-2 | Tvärstag | Anti-roll bar | | | | 1490 |
| 30 | 1 | - | - | 672226-8 | •Bussning | •Bushing | | | | 1500 |
| 31 | 1 | - | - | 675807-2 | •Bussning | •Bushing | | | | 1510 |
| 32 | 1 | - | - | 955569-9 | Skruv | Screw | | | | 1520 |
| 33 | 1 | - | - | 120804-0 | Bricka | Washer | | | | 1530 |
| 34 | 2 | - | - | 950356-6 | Mutter | Nut | | | | 0 |
| 35 | 1 | - | - | 675317-2 | Konsol | Bracket | | | 30) | 1550 |
| | 1 | - | - | 684313-0 | Konsol | Bracket | | | 31) | 1560 |
| 36 | 4 | - | - | 943885-4 | Skruv | Bolt | | | | 1570 |
| 37 | 4 | - | - | 940280-1 | Fjädrande bricka | Resilient washer | | | TID UTF. | 1580 |
| 38 | 2 | - | - | 675384-2 | Gummibuffert | Rubber cushion | | | 34) 142,144 | 1590 |
| | 2 | - | - | 683423-8 | Gummibuffert | Rubber cushion | | | 35) 142,144 | 0 |
| | 2 | - | - | 679555-3 | Hålgummifjäder | Hollow rubber spring | 8 | | 145 CH 30900-61624, EXCL 61600-61609. | 2010 |
| | 2 | - | - | 684873-3 | Hålgummifjäder | Hollow rubber spring | 8 | | 145 CH 61625- INCL 61600-61609. (940133) SEN. UTF. | 2020 |
| 39 | 4 | - | - | 943909-2 | Flänsskruv | Flange screw | | | TID UTF. | 2030 |
| 40 | 4 | - | - | 942336-9 | Fjäderbricka | Spring washer | | | (940133) SEN. UTF. | 2040 |
| 41 | 1 | - | - | 683538-3 | Gummibuffert | Rubber cushion | | | TID UTF. | 2050 |
| 42 | 1 | - | - | 950058-8 | Skruv | Screw | | | | 2060 |
| 43 | 1 | - | - | 955949-3 | Låsbricka | Lock washer | | | | 2070 |
| 44 | 2 | - | - | 688253-4 | Stötdämpare | Shock absorber | 8 | | MÄRKT 688253 | 2080 |
| | | | | | | | | | 142 CH-260324 EXCL | 2090 |
| | | | | | | | | | 259143-259292. | 2100 |
| | | | | | | | | | 144 CH-274585 EXCL | 2110 |
| | | | | | | | | | 272838-272942, | 2120 |
| | | | | | | | | | 273963-274501. | 2130 |
| | | | | | | | | | ERS AV 1ST 273355-8, | 2140 |
| | | | | | | | | | 1ST 272761-6. | 2150 |
| | | | | | | | | | MÄRKT 1210304,GT | 2160 |
| | 2 | - | - | 282698-0 | Stötdämpare | Shock absorber | | | 145 CH-116029 EXCL | 2170 |
| | 2 | - | - | 679599-1 | Stötdämpare | Shock absorber | 8 | | 110299-110393,111388- | 2180 |
| | | | | | | | | | 111441,112436-112584, | 2190 |
| | | | | | | | | | 113574-113675,114655- | 2200 |
| | | | | | | | | | 114704,115679-115832. | 0 |
| | | | | | | | | | ERS AV 1ST 273349-1, | 2220 |
| | | | | | | | | | 1ST 282761-6. | 2230 |
| | | | | | | | | | (1212110) | 2240 |
| x 45 | 2 | - | - | 273355-8 | Stötdämpare | Shock absorber | | | 142 CH 260325- INCL | 2250 |
| | | | | | | | | | 259143-259292. | 2260 |
| | | | | | | | | | 144 CH 274586- INCL | 1 |
| | | | | | | | | | 272838-272942, | 2270 |
| | | | | | | | | | 273963-274501. | 2280 |
| | | | | | | | | | (681763) 142-144, | 2290 |
| x | 2 | - | - | 273349-1 | Stötdämpare, förstärkt | Shock absorber, reinforced | | | MÄRKT 273349. | 2300 |
| | | | | | | | | | | 2310 |
| | | | | | | | | | | 2311 |

30. 142 CH 112400-178959. 144 CH 138700-194139, 194149-194391. 145 CH 61610-61624.
 31. 142 CH 178960-. 144 CH 194140-194148, 194302-. 145 CH 61600-61609, 61625-.
 32. 142 CH 112400- 148889. 144 CH 138700-168952. 145 CH 30900-47011.
 33. 142 CH 148890-. 144 CH 168953-. 145 CH 47012-.
 34. 142 CH 112400-178959. 144 CH 138700-194139, 194149-194301.
 35. 142 CH 178960-. 144 CH 194140-194148, 194302-.

| Sida Page | Grupp Group | Bakaxel,upphängning 142 CH 112400-,144 CH 138700- 145 CH 30900- | Rear axle,mountings 142 CH 112400-,144 CH 138700- 145 CH 30900- | Illustration 10841 1979-11 | 1550 | | | | | | |
|--------------|----------------|---|---|----------------------------------|-----------------------|--------------------------------------|---|-------------|------------------|--|--|
| Pos. Fig. | Antal/Quantity | | | | Artikel nr Part No | Benämning | Description | Sats Kit | B P S R | Anmärkning Notes | |
| x | 2 | - | - | - | 273349-1 | Stötdämpare | Shock absorber | | | (688261) 145 CH 116030-INCL 110299-110393,111388- 111441,112436-112584, 113574-113675,114655- 114704,115679-115832. | 2320 2321 2330 2340 2350 2360 2370 |
| 46 | 2 | - | - | - | 942760-0 | Skruv | Screw | S | | | 2380 |
| 47 | 2 | - | - | - | 940280-1 | Fjädrande bricka | Resilient washer | S | | | 2390 |
| 48 | 2 | - | - | - | 675874-2 | Distansrör | Spacer tube | S | | | 2400 |
| 49 | 4 | - | - | - | 89567-2 | Gummibussning | Rubber bushing | S | | SEN.UTF. | 2450 |
| 50 | 2 | - | - | - | 941857-5 | Skruv | Screw | S | | TID.UTF. | 2460 |
| x | 2 | - | - | - | 1221574-5 | Lagerbult | Bearing bolt | S | | (1212112) SEN UTF. | 2470 |
| 52 | 2 | - | - | - | 960145-1 | Bricka | Washer | S | | | 2430 |
| 53 | 2 | - | - | - | 950356-6 | Mutter | Nut | S | | TID.UTF. | 2440 |
| 54 | 4 | - | - | - | 950376-4 | Mutter | Nut | S | | SEN.UTF. | 2450 |
| 55 | 2 | - | - | - | 683916-1 | Bakfjäder | Rear spring | | | 142-144 | 2460 |
| | 2 | - | - | - | 677252-9 | Bakfjäder, förstärkt | Rear spring, reinforced | | | (678861) 142-144. | 2470 |
| | 2 | - | - | - | 677252-9 | Bakfjäder | Rear spring | | | 145 HV | 2480 |
| | 2 | - | - | - | 683290-1 | Bakfjäder | Rear spring | | | 145 HV,FÖRSTÄRKT, REINFORCED,145 SV | 2490 |
| | 2 | - | - | - | 1212231-3 | Bakfjäder | Rear spring | | | 46)145 HT | 2510 |
| 56 | 1 | - | - | - | 687457-2 | Distansbricka | Spacer washer | | | 145 CH 64531- INCL 64093-64172. | 2520 2530 |
| 57 | 2 | - | - | - | 675266-1 | Fjäderplatta | Spring plate | | | | 2540 |
| 58 | 2 | - | - | - | 676915-2 | Mellanlägg | Spacer | | | | 2550 |
| 59 | 2 | - | - | - | 675814-8 | Fästbricka | Anchorage washer | | | | 2560 |
| 60 | 2 | - | - | - | 955535-0 | Skruv | Screw | | | L 31,7 142-144 145 CH-64530 EXCL 64093-64172 | 2570 2580 2590 |
| | 1 | - | - | - | 944429-0 | Flänsskruv | Flange screw | | | 145 CH 64531-, INCL 64093-64172 | 3010 3020 |
| | 1 | - | - | - | 955536-8 | Skruv | Screw | | | L 45, 145 CH 64531-, INCL 64093-64172 | 3030 3040 |
| 61 | 1 | - | - | - | 942336-9 | Fjädrande bricka | Resilient washer | | | | 3050 |
| 62 | 2 | - | - | - | 675815-5 | Fästbricka | Anchorage washer | 8 | | ERS AV 1ST 1206811-0, 1ST 945654-2. | 3060 3061 |
| 63 | 2 | - | - | - | 950354-1 | Mutter | Nut | | | | 3070 |
| | 1 | - | - | - | 273016-6 | Monteringssats, stötdämpare | Installation kit, shock absorber | | | | 3090 |
| | 1 | - | - | - | 282761-6 | Monteringssats, stötdämpare | Installation kit, shock absorber | | 51) | | 3100 3110 |

46. Endast för vagnar med ett lägsta bakaxeltryck av 900 kg. Only for trucks with a lowest rear axle load of 900 kg. Seulement pour véhicules où le poids sous essieu arrière est au minimum de 900 kg. Nur für Wagen mit einer Hinterachslast von mindestens 900 kg. Sólo para vehículos con la menor presión sobre eje posterior de 900 kg.

51. Monteras vid övergång från tidigare till senare utförande av stötdämpare. Installed in conjunction with transition from earlier to late production shock absorbers. Doit être monté lorsqu'un amortisseur d'ancienne version est remplacé par un nouvel amortisseur. Wird beim Übergang von der alten auf die neue Stossdämpferausführung montiert. Se monta al hacer el cambio de silenciador de antiguo modelo al nuevo.