



VOLVO PARTS
 1090 16809



Sida Page	Grupp Group	Luftkonditionering B14			Air conditioning B14			Illustration 16809 1984-12	0260	
Pos. Fig.	Antal/Quantity			Artikel nr Part No	Benämning	Description	Sats Kit	B P S R	Anmärkning Notes	
1	1	-	-	-	284586-5	Luftkonditionerings- sats	Air conditioning kit		CH -556247	0020
	1	-	-	-	284586-5	Luftkonditionerings- sats	Air conditioning kit		1) CH 556248-	0040 0060 0080
	1	-	-	-	284586-5	Luftkonditionerings- sats	Air conditioning kit		1,8) CH 610000-	0100 0120
2	1	-	-	-		.Vakuüm- och el. utrustning	.Vacuum and electrical equipment		SE SIDA 28, 4-B05	0140 0160
3	1	-	-	-	3298242-3	.Anslutning	.Connection	5		0180
4	1	-	-	-	3298247-2	.Slang	.Hose	5		0200
5	1	-	-	-		.Evaporator	.Evaporator		SE SIDA 30, 4-B07	0220
6	1	-	-	-	3277853-2	.Hus	.Housing	5		0240
7	1	-	-	-	3298249-8	.Slang	.Hose	5		0260
8	1	-	-	-	3298227-4	.Dräneringsslang	.Drain hose	5		0280
9	1	-	-	-	3298180-5	.Slang	.Hose	5		0290
10	1	-	-	-	3298181-3	.Slang	.Hose	5		0320
11	2	-	-	-	943479-6	.Slangklamma	.Hose clamp	2	DI 42 MM, (3277857)	0340
	1	-	-	-	3277858-1	.Slangklamma	.Hose clamp	5	D1 22 MM	0360
12	1	-	-	-		.Kompressor med upphängning	.Compressor with mountings		SE SIDA 32, 4-B09	0380 0400 0420
13	1	-	-	-	3298179-7	.Slang	.Hose	5		0440
14	1	-	-	-		.Kondenser	.Condenser		SE SIDA 32, 4-B09	0460
15	1	-	-	-	3298182-1	.Slang	.Hose	5		0480
16	1	-	-	-	3298177-1	.Torkare	.Receiver-drier	5		0500
17	1	-	-	-	3298113-6	.Klamma	.Clamp	5		0520
18	2	-	-	-	955272-0	.Skruv	.Screw	2		0540
19	1	-	-	-	1161225-6	.Kylmedium	.Cooling agent	6		0560
20	1	-	-	-	1159799-4	.Påfyllningsnippel	.Filling nipple	6	(1207357)	0580
21	1	-	-	-	3298241-5	.Anslutning	.Connection	5		0600
	1	-	-	-	284661-6	Spjällsats	Shutter kit	4	CH 556248-	

- Spjällsats 284661-6 måste beställas separat. Shutter kit 284661-6 should be ordered additionally. Régulateur 284661-6 doit tre commandé séparément. Drosselklappensatz 284661-6 ist getrennt zu bestellen. El juego de válvulas 284661-6 debe pedirse por separado. Il kit della farfalla di apertura 284661-6 deve ordinarsi separatamente.
- Vevaxelremskiva 3283641-3 och distansbricka 3286783-0 måste beställas separat. Crankshaft pulley 3283641-3 and spacer washer 3286783-0 should be ordered additionally. La poulie d'entraînement de vilebrequin 3283641-3 et la rondelle d'écartement 3286783-0 doivent tre commandés séparément. Kurbelwellenriemenscheibe 3283641-3 und Abstandscheibe 3286783-0 müssen separat bestellt werden. La polea del cigueñal 3283641-3 y la arandela de distancia 3286783-0 han de solicitarse por separado. La puleggia, dell'albero motore per la cinghia trapezoidale 3283641-3 e la rondella 3286783-0 debbono ordinarsi separatamente.