









VOLVO
Genuine Parts
PV520 43869

A						REPARATIONSSATS VAKUUMPUMP SERVOCYLINDER		REPARATURSÄTZE VAKUUMPUMPE SERVOZYLINDER		Grupp Gruppe 52 Sida Seite 1173	
B											
C											
D											
E											
Pos	Artikel nr Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	272586-9	1	-	-	-	-		Ventilsats	Ventilsatz	B28	3
2	272587-7	1	-	-	-	-		Membransats	Membransatz	B28	3
3	272647-9	1	-	-	-	-		Hävarmsats	Hebelsatz	B28	3
4	272722-0	1	-	-	-	-		Reparationssats byte av tätningselement	Reparatursatz Austausch von dichtelem.	DSL	3
5	272723-8	1	-	-	-	-		Reparationssats byte av ventiler	Reparatursatz Austusch von Ventilen	DSL	3
6	270596-0	1	-	-	-	-		Ventilsats	Ventilsatz		2