









VOLVO
Genuine Parts
PV520 43869

A							REPARATIONSSATS VAKUUMPUMP SERVOCYLINDER		REPARATURSÄTZE VAKUUMPUMPE SERVOZYLINDER		Grupp Gruppe	
B											52	
C											Sida Seite	
D											853	
E												
Pos	Artikelnummer Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R	
		A	B	C	D	E						
1	272586-9	1	-	-	-	-		Ventilsats	Ventilsatz	B28		3
2	272587-7	1	-	-	-	-		Membransats	Membransatz	B28		3
3	272647-9	1	-	-	-	-		Hävarmsats	Hebelsatz	B28		3
4	272722-0	1	-	-	-	-		Reparationssats byte av tätningselement	Reparatursatz Austausch von dichtelem.	DSL		3
5	272723-8	1	-	-	-	-		Reparationssats byte av ventiler	Reparatursatz Austusch von Ventilen	DSL		3
6	270596-0	1	-	-	-	-		Ventilsats	Ventilsatz			2