




VOLVO
Genuine Parts
PV 360 55744

A							WINDSCREEN WIPERS		VINDRUTETORKARE		Group Grupp	
B											36	
C											Page Sida	
D											451	
E									ELEKTROLUX			
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R	
		A	B	C	D	E						
1		1	-	-	-	-	NS	Windscreen wiper complete ...	Vindrutetorkare komplett			
2	3518131-2	1	-	-	-	-		• Transmission	• Transmission		4	
3	1358181-4	2	-	-	-	-		Bearing	Lager		3	
4	3518148-6	1	-	-	-	-		• Bushing	• Bussning		4	
5	3518145-2	1	-	-	-	-		• Crank arm	• Vevarm		4	
6	3518146-0	1	-	-	-	-		• Link arm	• Länkarm		4	
7	3518268-2	1	-	-	-	-		• Companion flange	• Medbringare		4	
8	3518269-0	1	-	-	-	-		• O-ring	• O-ring		3	
9	687784-9	1	-	-	-	-		• Seal	• Tätning		3	
10	963104-5	1	-	-	-	-		• Cable	• Lina		3	
11	1304975-4	2	-	-	-	-		• Lock nut	• Låsmutter		2	
12	3518133-8	1	-	-	-	-		• Cover	• Kåpa		3	
13	944637-8	1	-	-	-	-		• Motor	• Motor		2	
14	1259831-4	1	-	-	-	-		• Sealing ring	• Tätningsring		2	
15	955269-6	4	-	-	-	-		• Pin housing	• Stiftisolator		2	
16	955892-5	4	-	-	-	-		• Screw	• Skruv		2	
17	961407-4	1	-	-	-	-		• Washer	• Bricka		2	
18	948211-8	1	-	-	-	-		• Disc spring	• Tallriksfjäder		2	
19	975561-2	1	-	-	-	-		• Strip clamp	• Bandklamma		2	
20	1342099-7	1	-	-	-	-		Flange screw	Flänsskruv	(973475)	1	
21	94081-7	1	-	-	-	-		Mudflap	Stänkskydd		4	
22	1392060-8	4	-	-	-	-		Plug	Plugg		3	
23	945444-8	2	-	-	-	-		Spacer sleeve	Distanshylsa		3	
24	1396436-6	2	-	-	-	-		Flange screw	Flänsskruv	(967573)	2	
25	1341510-4	1	-	-	-	-		Seal	Tätning	L.H.	3	
26	1342289-4	1	-	-	-	-		Seal	Tätning	R.H.	3	
27	3538316-5	2	-	-	-	-		Support	Stöd		3	
28	3538351-2	1	-	-	-	-		Wiper arm	Torkararm	(1392931). BOSCH	2	
29	1392918-7	2	-	-	-	-		• Cover	• Täckkåpa	BOSCH	3	
30	968862-3	2	-	-	-	-		Cover	Täckkåpa	TRICO	3	
31	1392518-5	2	-	-	-	-		Flange nut	Flänsmutter	(955782)	8	
32	1392920-3	2	-	-	-	-		Wiper blade	Torkarblad	BOSCH	1	
33	3407212-4	1	-	-	-	-		Wiper blade	Torkarblad	TRICO	1	
34	3518997-6	1	-	-	-	-		Bushing	Bussning	1991-	3	
35		1	-	-	-	-		Seal	Tätning	1991-	3	