



VOLVO

WORKSHOP BULLETIN

CARS

RE:	PRODUCT
OVERDRIVE	P
	GROUP
	43
	NO.
DATE	12
July 1965	

Guide pin for spring for check valve.

It has been found that the spring for the check valve of the pump can come askew which results in the ball being pushed to one side so that it does not seal against the seat. In order to avoid this a new guide pin, part number 907181, has been introduced in production.

This guide pin should be fitted on earlier overdrives when reconditioning or in the event of the above-mentioned trouble occurring. It is fitted as shown in the figure.

The guide pin has been introduced in production with effect from:

P 1800	overdrive	manufacturing	serial number	5643	onwards
P 120	"	"	"	"	11238 onwards

