



Grupp Group		3		P 120 P 130 P 220(B18)			VOLVO		
Sida Page		8		Utgåva Issue		10		Reservdelskatalog Parts catalogue	
Pos Fig.	Antal Qty.		Benämning	Description	Det. nr Part No.	Anmärkning Notes			
	B188 Vst	B188 Hst							
1	1	1	Växelströmsgenerator . Det se sida 10	Alternator . Components, see page 10	419420-5				
2	3	3	Fjädrande bricka	Resilient washer	941905-2				
3	3	3	Mutter	Nut	955844-6				
4	1		Skruv	Screw	955565-7	1 = 57			
5	1		Fjädrande bricka	Resilient washer	940280-1				
6	1		Spännjärn	Tensioner arm	419376-9				
7	1		Skruv	Bolt	955523-6	1 = 16			
8	1		Skruv	Bolt	955524-4	1 = 19			
9	1		Bricka	Washer	191172-6				
10	1		Drivrem	Drive belt		Se grupp 2b			
11		1	Konsol	Bracket	419417-1				
12		1	Skruv	Bolt	955535-0	1 = 32			
13		1	Skruv	Bolt	955536-8	1 = 45			
14		1	Skruv	Bolt	955565-7	1 = 57			
15		1	Fjädrande bricka	Resilient washer	940280-1				
16		1	Spännjärn	Tensioner arm	419418-9				
17		1	Skruv	Bolt	940133-2	1 = 16			
18		1	Skruv	Bolt	955524-4	1 = 19			
19		1	Bricka	Washer	191172-6				
20		1	Drivrem	Drive belt		Se grupp 2b			
21	1	1	Laddningsregulator	Charging relay	419444-5	1)			
22	2	2	Skruv	Screw	958236-2	1)			
23	2	2	Fjädrande bricka	Resilient washer	941906-0	1)			
24	1	1	Laddningsregulator	Charging relay	419589-7	2)			
25	2	2	Skruv	Screw	958236-2	2)			
26	2	2	Fjädrande bricka	Resilient washer	941906-0	2)			
27	1	1	Fjädrande bricka	Resilient washer	941904-5	2)			
28	1	1	Mutter	Nut	955779-4	2)			
29	1	1	Varningskylt	Warning plate	672765-5	Lagerföres ej			

- För fordon med kommunikationsradio.  
For vehicles with shortwave transmitters.  
Pour véhicules avec radiocommunication.  
Für Wagen mit Sprechfunk.  
Para coches con equipo de radiocomunicaciones.
- För fordon utan kommunikationsradio.  
For vehicles not fitted with shortwave transmitters.  
Pour véhicules sans radiocommunication.  
Für Wagen ohne Sprechfunk.  
Para coches sin equipo de radiocomunicaciones.