



VOLVO
KA7872

Grupp Group		4		P 110 P 210(B18)			VOLVO		
Sida Page		30		Utgåva Issue		5		Reservdelskatalog Parts catalogue	
				Bakaxel		Rear axle			
Pos Fig.	Antal Qty.		Benämning	Description	Def. nr Part No.	Anmärkning Notes			
	667340	255492							
1	1		Bakaxel, utv 4,1:1	Rear axle, ratio 4.1:1	667340-4				
		1	Bakaxel, utv 4,56:1	Rear axle, ratio 4.56:1	255492-1				
2	1		. Bakaxelkåpa Rear axle casing	660080-3				
3	1		. Bakaxelkåpa Rear axle casing	384357-0				
4	2	2	. . Överfall Cap	S E S				
5	4	4	. . Skruv Screw	955551-7	921864			
6	1	1	. Inspektionslock Inspection cover	89253-9				
7	1	1	. . Propp Plug	952359-8				
8	1	1	. Packning Gasket	89254-7				
9	10	10	. Skruv Screw	955523-6	921822			
10	10	10	. Lösbricka Lock washer	955949-3				
11	1		. Differential Differential	661516-5	1)			
		1	. Differential Differential	384196-2	2)			
12	1		. . Hus Housing	661515-5				
		1	. . Hus Housing	384199-6				
13	2		. . Differentialhjul Side pinion	89673-8				
		2	. . Differentialhjul Side pinion	384206-9				
14	2		. . Tryckbricka Thrust washer	658620-0				
		2	. . Tryckbricka, tj = 0,78 Thrust washer, Th = 0.78 ...	384366-1				
		2 tj = 0,82 Th = 0.82 ...	384367-9				
		2 tj = 0,86 Th = 0.86 ...	384368-7	Alt			
		2 tj = 0,90 Th = 0.90 ...	384369-5				
		2 tj = 0,94 Th = 0.94 ...	384370-3				
15	2		. . Differentialhjul Side gear	89674-6				
		2	. . Differentialhjul Side gear	384204-4				
16	2		. . Tryckbricka Thrust washer	87651-6				
		2	. . Tryckbricka Thrust washer	384209-3				
17	1		. . Axeltapp Shaft pin	89949-2	89259			
		1	. . Axeltapp Shaft pin	384201-0				
18	1	1	. . Låspinne Lock pin	191838-2				
19	1		. . Distanshylsa Spacer sleeve	87648-2				
		1	. . Distanshylsa Spacer sleeve	384202-8				

- Vid byte till "Anti-Spinn" skall differential 666244-9 monteras. Se sida 40.
With transition to "Anti-Spinn" differential 666244-9 must be installed. See page 40.
Lors du remplacement par "Anti-Spinn" le différentiel 666244-9 doit être monté. Voir page 40.
Beim Austausch zu "Anti-Spinn" muss Ausgleichgetriebe 666244-9 eingebaut werden. Siehe Seite 40.
Al montarse el "Anti-Spinn" se deben también montar el diferencial 666244-9. Véase pág. 40.
- Vid byte till "Anti-Spinn" skall differential 384479-2 monteras. Se sida 40.
With transition to "Anti-Spinn" differential 384479-2 must be installed. See page 40.
Lors du remplacement par "Anti-Spinn" le différentiel 384479-2 doit être monté. Voir page 40.
Beim Austausch zu "Anti-Spinn" muss Ausgleichgetriebe 384479-2 eingebaut werden. Siehe Seite 40.
Al montarse el "Anti-Spinn" se deben también montar el diferencial 384479-2. Véase pág. 40.

