



VOLVO PARTS
1080 12197



Sida	Grupp	Stötfångare excl USA, CAN.	Bumpers excl USA, CAN.	Illustration 12197	1450					
92	8	142 CH 393950-, 144 CH 428000- 145 CH 210050-	142 CH 393950-, 144 CH 428000- 145 CH 210050-	1975-01						
Page	Group									
Pos. Fig.	Antal/Quantity				Detalj nr Part No	Benämning	Description	Sats Kit	Anmärkning Notes	
1	1	-	-	-	1213536-4	Stötfångare, främre	Bumper, front			1010
2	2	-	-	-	1213692-5	Bärjärn	Support arm		EXCL JAPAN	1020
	2	-	-	-	1203704-0	Bärjärn	Support arm		JAPAN	1025
3	4	-	-	-	955561-6	Skruv	Screw			1030
4	4	-	-	-	960145-1	Bricka	Washer			1040
5	2	-	-	-	1213698-2	Dämpare	Energy absorber			1050
6	2	-	-	-	1203142-3	Styrhylsa	Sleeve			1060
7	2	-	-	-	1203225-6	Fäste	Anchorage			1070
8	2	-	-	-	963108-6	Mutter	Nut			1080
9	2	-	-	-	955897-4	Bricka	Washer			1090
10	2	-	-	-	1213694-1	Fäste	Anchorage			1100
11	4	-	-	-	955783-6	Mutter	Nut		TID UTF M10	1110
	4	-	-	-	945409-1	Flänsmutter	Flange nut		SEN UTF M10	
12	4	-	-	-	960148-5	Bricka	Washer		TID UTF	1120
13	4	-	-	-	955315-7	Skruv	Screw			1130
14	4	-	-	-	960148-5	Bricka	Washer			1140
15	1	-	-	-	1213629-7	Stötfångarlist, V	Bumper moulding, L		EXCL EEC	1150
	1	-	-	-	1203319-7	Stötfångarlist, V	Bumper moulding, L		EEC	1160
	1	-	-	-	1213630-5	Stötfångarlist, H	Bumper moulding, R		EXCL EEC	
	1	-	-	-	1203320-5	Stötfångarlist, H	Bumper moulding, R		EEC	1180
16	1	-	-	-	1213812-9	Stötfångarlist, mitt	Bumper moulding, centre			1190
17	2	-	-	-	1213632-1	Hållare, yttre	Retainer, outer			1200
18	1	-	-	-	1213813-7	Hållare, mitt	Retainer, centre			1210
19	22	-	-	-	958236-2	Skruv	Screw			1220
20	2	-	-	-	955139-1	Skruv	Screw			1230
21	2	-	-	-	947739-9	Plastmutter	Plastic nut			1240
22	4	-	-	-	1203680-2	Clips	Clip		(1203165)	1250
23	1	-	-	-	1203159-7	Täckkäpa, V	Rubber boot, L			1260
	1	-	-	-	1203160-5	Täckkäpa, H	Rubber boot, R			1270
24	1	-	-	-	1203291-8	Stöd, V	Support, L			1280
	1	-	-	-	1203292-6	Stöd, H	Support, R			1290
25	4	-	-	-	955141-7	Skruv	Screw			1300
26	1	-	-	-	1213538-0	Stötfångare, bakre	Bumper, rear			1310
27	2	-	-	-	1213686-7	Bärjärn	Support arm		EXCL JAPAN	1320
	2	-	-	-	1203706-5	Bärjärn	Support arm		JAPAN	1325
28	2	-	-	-	1213698-2	Dämpare	Energy absorber			1330
29	2	-	-	-	1203142-3	Styrhylsa	Sleeve			1340
30	2	-	-	-	1203225-6	Fäste	Anchorage			1350
31	2	-	-	-	963108-6	Mutter	Nut			1360
32	2	-	-	-	955897-4	Bricka	Washer			1370
33	2	-	-	-	1203195-1	Styrbricka	Guide bracket			1380
34	2	-	-	-	1203196-9	Mellanlägg	Spacer			1390
35	4	-	-	-	940133-2	Skruv	Screw			1400
36	4	-	-	-	960141-0	Bricka	Washer			1410
37	2	-	-	-	962912-2	Skruv	Screw			1420
37a	2	-	-	-	955899-0	Bricka	Washer			
38	2	-	-	-	1213690-9	Fäste	Anchorage			1430
39	4	-	-	-	955783-6	Mutter	Nut		TID UTF M10	1440
	4	-	-	-	945409-1	Flänsmutter	Flange nut		SEN UTF M10	1445
40	4	-	-	-	960148-5	Bricka	Washer		TID UTF	1450
41	4	-	-	-	955315-7	Skruv	Screw			1460
42	4	-	-	-	960148-5	Bricka	Washer			1470
43	1	-	-	-	1213639-6	Stötfångarlist, V	Bumper moulding, L			1480
	1	-	-	-	1213640-4	Stötfångarlist, H	Bumper moulding, R			1490
44	1	-	-	-	1213641-2	Stötfångarlist, mitt	Bumper moulding, centre			1500
45	2	-	-	-	1213642-0	Hållare	Retainer			1510
46	20	-	-	-	958236-2	Skruv	Screw			1520
47	4	-	-	-	1203165-4	Clips	Clip			1530
48	1	-	-	-	1213643-8	Täcklist, V	Cover moulding, L			1540
	1	-	-	-	1213644-6	Täcklist, H	Cover moulding, R			1550
49	1	-	-	-	1203279-3	Hållare, V	Retainer, L			1560
	1	-	-	-	1203280-1	Hållare, H	Retainer, R			1570
50	2	-	-	-	945407-5	Mutter	Nut			1580



Sida 94	Grupp 8	Stötfångare excl USA, CAN. 142 CH 393950-, 144 CH 428000- 145 CH 210050-	Bumpers excl USA, CAN. 142 CH 393950-, 144 CH 428000- 145 CH 210050-	Illustration 12197 1975-01	1450
-------------------	-------------------	--	--	-------------------------------	------

Pos. Fig.	Antal/Quantity			Detalj nr Part No	Benämning	Description	Sats Kit	Anmärkning Notes	
51	2	-	-	955892-5	Bricka	Washer			1590
52	1	-	-	1213645-3	Täcklist, mitt	Cover moulding, centre			1600
53	1	-	-	1203085-4	Stöd	Support			1601
54	3	-	-	1203156-3	Clips	Clip			1602