



VOLVO PARTS
 1030 16458

Sida Page	Grupp Group	Vindrutetorkare SWF	Windscreen wiper SWF	Illustration 16458 1983-03	0425						
28	3										
Pos. Fig.	Antal/Quantity				Artikel nr Part No	Benämning	Description	Sats Kit	B P S R	Anmärkning Notes	
1	1	-	-	-	3269122-2	Vindrutetorkar- motor kpl	Windscreen wiper motor cpl	2			0020
1a	1	-	-	-		.Vindrutetorkar- motor	.Windscreen wiper motor	8			0040 0050 0055
2	1	-	-	-	3276173-6	.Konsol	.Bracket	3			0060
3	1	-	-	-	3276174-4	.Gummiring	.Rubber ring	3			0080
4	3	-	-	-	955948-5	.Låsring	.Lock ring	2			0100
5	3	-	-	-	956094-7	.Skriv	.Screw	2			0120
6	1	-	-	-	3277526-4	.Vevarm	.Crank arm	4			0140
7	1	-	-	-	3275391-5	.Mutter	.Nut	2			0150
8	3	-	-	-	955272-0	Skruv	Screw	2			J
9	3	-	-	-	3276161-1	Bricka	Washer	2			0200
10	3	-	-	-	3276176-9	Hylsa	Spacer	3			0220
11	3	-	-	-	3276177-7	Tätning	Grommet	3			0240
12	1	-	-	-	3276170-2	Drivlänk	Connecting rod	3			0260
13	1	-	-	-	3276557-0	Skruv	Screw	2			0280
14	1	-	-	-	941906-0	Låsring	Lock ring	2)
15	1	-	-	-	3277497-8	Torkararmslager, V	Pivot spindle, L	3			0320
16	1	-	-	-	3277498-6	Torkararmslager, H	Pivot spindle, R	3			0340
17	4	-	-	-	956076-4	Skruv	Screw	2			0360
18	4	-	-	-	942604-0	Fjäderbricka	Spring washer	2			0380
19	2	-	-	-	3101439-2	Gummiring	Rubber ring	2			0400
20	2	-	-	-	3273827-0	Bricka	Washer	3			0420
21	2	-	-	-	3274265-2	Mutter	Nut	3			0440
22	2	-	-	-	3276180-1	Överfall	Cap	3			0460
23	2	-	-	-	3273235-6	Bricka	Washer	2			0480
24	2	-	-	-	3105391-1	Mutter	Nut	2			0500
25	1	-	-	-	3276169-4	Drivlänk	Connecting rod	3			0520
26	2	-	-	-	3273768-6	Torkararm	Wiper arm	1			0540
27	2	-	-	-	3273769-4	Torkarblad	Wiper blade	1			0560
27a	2	-	-	-	3277711-2	.Gummiblåd	.Rubber blade	1	TRICO		0580