

72 E WIRING




ILLUSTRATION 3-A. WIRING DIAGRAM 1800 E