

Electrical equipment

<u>Description</u>	<u>Part No.</u>	<u>Qty.</u>
Bracket on dashboard	86540 ¹⁾	2
. Screw, self-tapping	13179	8
. . Lock washer	951696	8
Bracket for horn	88569 ¹⁾	2
. Spacer ring	88568	4
. . Nut	151206	4
. . Spring washer	17890	4
Screw for horn	902251 ¹⁾	4
. . Spring washer	906987	4
Cover plate for air duct (in front section)	88448 ¹⁾	1
. Screw, self-tapping	13173	2
<u>Horn</u> , high tone, Bosch HO/FDF 6/46	76784	1
Horn, low tone, Bosch HO/FDF 6/49	77721 ²⁾	1
Horn, low tone, Bosch HO/FDF 6/45	76785 ³⁾	1
Nut for horn	150133 ⁴⁾	2
. Washer, 10,5 x 40 x 5 mm	87506	2
. Washer, 14,5 x 38 x 3 mm	18702	2
. Rubber bushing	66089	2
<u>Relay for horn</u>	88459 ⁵⁾	1
. Screw, self-tapping	13173	2
. . Base washer	120098	2
<u>Headlight insert</u> , complete, Bosch: B 20/165	77583 ⁶⁾	2
. Reflector, complete with lens, B 20/11	77595	2
. . Lens	N.S.S.	
. Bulb socket, complete, B 20/12	77596	2
. . Connecting screw	14101	2
. . Spring for bulb socket, B 20/13	77597	2

1. P 44404 with chassis Nos. 12005-28004.

2. P 44404 with chassis Nos. 28005-55397.

3. P 44404 with chassis Nos. 55398-131917.

4. P 44404 with chassis Nos. 28005-131917.

5. P 44404 with chassis Nos. 12005-131917.

6. Up to chassis No. 28004. Replaced by headlight insert No. 77804.

Electrical equipment

<u>Description</u>	<u>Part No.</u>	<u>Qty.</u>
<u>Headlight insert</u> , complete, Bosch: B 24/165	77804 ¹⁾	2
. Reflector, complete with lens, B 24/11	76519	2
. . Lens	N.S.S.	
. Bulb socket, complete, B 20/12	77596	2
. . Connecting screw	14101	8
. Spring for bulb socket, B 20/13	77597	2
<u>Headlight insert</u> , complete, Bosch: B 26/165	76831 ²⁾	2
. Reflector with lens and gasket, B 26/11	233169	2
. Bulb socket, complete, B 26/12	233168	2
. . Connecting screw	14101	8
. Spring for bulb socket, B 26/13	233170	2
Bulb for full and dipped headlights	182035	2
Bulb for parking light	11497	2
Retainer for headlight insert	88050	2
. Seal ring	88052	2
Screw, retainer - sliding cap	115481	6
. Lock washer	951692	6
<u>Rim</u> for headlight insert	88049	2
. Screw	115895	2
Sliding cap for headlight insert	83590	2
. Spring, sliding cap-protector cover for headlight insert	83591	8
. Adjuster screw for sliding cap	87690	4
<u>Protector cover</u> , complete, left, for headlight insert	87680	1
Protector cover, complete, right, for headlight insert	87681	1
. Nut	83587	4
Rubber seal for protector cover	88051	2
Screw for protector cover	902225	8
. Nut	906574	8
. Lock washer	951693	8
Screw, self-tapping	13173	4
Rubber bushing for cables in protector cover	87687	2
<u>Lamp</u> , complete, for number plate lighting	88561	1
. Gasket	88559	1
. Lens	88558	1
Screw for lamp	115494	2
. Nut	151223	2
1. For chassis Nos. 28005-68955.		
2. From chassis No. 68956 onwards.		

<u>Description</u>	<u>Part No.</u>	<u>Qty.</u>
. Spring washer	906985	2
Socket for bulb	30084	1
. Bulb	182007	1
Rubber cover for socket	88674	1
<u>Stop and tail light, left and right, complete, consisting of:</u>		
. Housing, left	87978 ¹⁾	1
. Housing, right	87979 ¹⁾	1
. . Lens	94101 ¹⁾	2
. . . Gasket	87722 ¹⁾	2
. . . Clamp	87721 ¹⁾	4
. . . . Screw, self-tapping	14923 ¹⁾	4
. Screw for housing	115875 ¹⁾	2
. Retainer, complete, for housing and bulb	87714 ²⁾	1
. . Screw for cable connection	915590	4
. Retainer, complete, for housing and bulb	89045 ³⁾	2
. . Screw for cable connection	14940	4
. Rubber spacer for retainer	87723 ¹⁾	2
. Nut for retainer	151215 ¹⁾	4
. . Base washer	11961 ¹⁾	4
. . Lock washer	951696 ¹⁾	4
. Bulb (in conjunction with retainer No. 87714)	19924	2
. Bulb (in conjunction with retainer No. 89045)	19897	2
Stop and tail light, left, complete, Bosch: B 87	76881 ⁴⁾	1
Stop and tail light, right, complete, Bosch: B 86	76882 ⁴⁾	1
. Housing, left, B 87/11	76844	1
. . Rubber base, B 87/10	76846	1
. Housing, right, B 86/11	76845	1
. . Rubber base, B 86/10	76847	1
Bulb for stop and tail light	19897	2
Nut for stop and tail light	120403 ⁴⁾	6

1. Up to chassis No. 68955.
2. Up to chassis No. 26686. Replaced by 1 retainer No. 89045, 1 bulb No. 19897 and 1 connector No. 182010.
3. For chassis Nos. 26687-68955.
4. From chassis No. 68956 onwards.