



**VOLVO**  
**KA 8139**



Sida 14 Grupp 6 Länkarm Wishbone Illustration 8139 0150  
Page 14 Group 6 1975-01

Pos. Fig.	Antal/Quantity				Detalj nr Part No	Benämning	Description	Sats Kit	Anmärkning Notes	
	688									
1	1	-	-	-	688021-5	Länkarm .....	Wishbone .....	1		1010
2	1	-	-	-	675098-8	•Axel .....	•Shaft .....	2		1020
3	2	-	-	-	675432-9	•Gummibussning .....	•Rubber bushing .....	1		1030
4	2	-	-	-	676053-2	•Bricka .....	•Washer .....	1		1040
5	2	-	-	-	950366-5	•Mutter .....	•Nut .....	0		1050
6	1	-	-	-	686398-9	•Kulled .....	•Ball socket .....	S	ALT 1.	1060
7	1	-	-	-	680829-9	••Hylsa .....	••Sleeve .....	S		1070
8	1	-	-	-		••Gummikåpa .....	••Rubber boot .....	S		1080
9	1	-	-	-	682786-9	••Spännring .....	••Tensioner ring .....	S		1090
10	1	-	-	-	682680-4	••Spännring .....	••Tensioner ring .....	S		1100
11	1	-	-	-	686500-0	•Kulled .....	•Ball socket .....	8	ALT 2. ERS AV 686398-9	1110
12	1	-	-	-		••Gummikåpa .....	••Rubber boot .....	8		1120
13	1	-	-	-	679207-1	••Låsring .....	••Circlip .....	2		1130
	2	-	-	-	273209-7	Kulledssats .....	Ball joint kit .....	1		1140