



1



VOLVO  
KA 6656

Sida	Grupp	Sekundärcylinder			Slave cylinder			Illustration 6656	0250
12	4							1974-08	
Page	Group								
Pos. Fig.	Antal/Quantity				Detalj nr Part No	Benämning	Description	Sats Kit	Anmärkning Notes
1	1	-	-	-	679155-2	Sekundärcylinder .....	Slave cylinder .....	2	1010
2	1	-	-	-		•Hus .....	•Housing .....	8	1020
3	1	-	-	-		•Kolv .....	•Piston .....	8	1030
4	1	-	-	-		•Packning .....	•Packing .....	8	1040
5	1	-	-	-	681870-2	•Låsring .....	•Circlip .....	2	1050
6	1	-	-	-		•Gummikåpa .....	•Rubber boot .....	8	1060
7	1	-	-	-	681871-0	•Låsring .....	•Lock ring .....	2	1070
8	1	-	-	-	681872-8	•Låsring .....	•Lock ring .....	2	1080
9	1	-	-	-	681873-6	•Tryckstång .....	•Push rod .....	3	1090
10	1	-	-	-	681874-4	•Luftningsnippel .....	•Air venting nipple .....	1	1100
11	1	-	-	-		••Gummikåpa .....	••Rubber boot .....	8	1110
	1	-	-	-	273119-8	Reparationssats .....	Reconditioning kit .....	1	1120