



VOLVO
Genuine Parts
PV 84044619

A	B	C	D	E	WINDSCREEN, REAR WINDOW AND DOOR PARE-BRISE, BAIE ARRIERE, BAIES LATERALES					Group		
					WINDOWS					84		
					5DRS					Page		
										1411		
Fig	Part No. No de réf.	Quantity / Nombre					P S	Description	Designation	Notes Remarques	S R	
		A	B	C	D	E						
1	1247924-2	1	-	-	-	-	OP	Windscreen	Pare-brise	1)		2
	1247925-9	1	-	-	-	-		Windscreen	Pare-brise	2)		3
	1246661-1	1	-	-	-	-		Windscreen with smoky stripe	Pare-brise avec bande teintée .	2)		3
	1247926	1	-	-	-	-		Windscreen	Pare-brise	3)		3
2	273923-3	1	-	-	-	-	Butyl tape windscreen replacement	Scotch butyle échange pare-brise			2	
3	1161156-3	1	-	-	-	-	Glass primer	Appret verre			6	
4	1161343-7	1	-	-	-	-	Sealant	Produit etancheite	(686275)		3	
5	1213056-3	1	-	-	-	-	Windscreen	Pare-brise			3	
	1213058-9	1	-	-	-	-	Glass, l.h.	Vitre, g	1)		3	
	1213057-1	1	-	-	-	-	Glass, l.h.	Vitre, g	2)		3	
	1213059-7	1	-	-	-	-	Glass, r.h.	Vitre, d	1)		3	
6	1213674-3	1	-	-	-	-	Glass, r.h.	Vitre, d	2)		3	
	1213676-8	1	-	-	-	-	Glass, l.h.	Vitre, g	1)		3	
	1213676-8	1	-	-	-	-	Glass, l.h.	Vitre, g	2)		3	
	1213675-0	-	-	-	-	-	Glass, r.h.	Vitre, d	1)		3	
7	1213677-6	1	-	-	-	-	Glass, r.h.	Vitre, d	2)		3	
	1203326-2	1	-	-	-	-	Side window glass, l.h.	Vitre laterale, g	1)		3	
	1213550-5	1	-	-	-	-	Side window glass, l.h.	Vitre laterale, g	2)		4	
	1203327-0	1	-	-	-	-	Side window glass, r.h.	Vitre laterale, d	1)		3	
8	1213551-3	1	-	-	-	-	Side window glass, r.h.	Vitre laterale, d	2)		4	
	1372174-1	1	-	-	-	-	Sealing strip, l.h.	Joint etancheite, g			3	
	1372175-8	1	-	-	-	-	Sealing strip, r.h.	Joint etancheite, d			3	
	1312609-9	1	-	-	-	-	Rear window	Lunette ar	1) (1203331)		3	
9	1372200-4	1	-	-	-	-	Rear window	Lunette ar	2)		3	
	1211139-9	1	-	-	-	-	Sealing strip	Lisse etancheite			3	

- 1) Clear glass. / Verre non coloré.
 2) Tinted glass. / Verre coloré.
 3) With radio antenna. / Avol antenne radio.