



VOLVO
 Genuine Parts
 PV 360 45966

A							WINDSCREEN WIPERS		VINDRUTETORKARE		Group Grupp
B											36
C											Page Sida
D											457
E									R.H.D		
Fig	Part No. Artikel nr	Quantity /Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
★ 1	1372359-8	1	-	-	-	-	NS	Wiper motor complete	Torkarmotor komplett		2
2	1247805-3	1	-	-	-	-		• Contact housing	• Kontakthus		3
3		1	-	-	-	-		Bushing	Bussning		3
4	1312822-8	6	-	-	-	-		Washer	Bricka		3
5	946934-7	3	-	-	-	-		Flange screw	Flänsskruv		2
6	1372307-7	1	-	-	-	-	Wiper mechanism complete ..	Torkarmekanism komplett		4	
7	687786-4	1	-	-	-	-	• Link arm	• Länkarm		3	
8	1203407-0	1	-	-	-	-	• Wiper link	• Drivlänk		3	
9	1372312-7	1	-	-	-	-	• Wiper bearing, l.h.	• Torkarlagar, v		3	
10	1372316-8	1	-	-	-	-	• Wiper bearing, r.h.	• Torkarlagar, h		3	
11	1304975-4	1	-	-	-	-	• • Cover	• • Kåpa		3	
12	687781-5	1	-	-	-	-	• Crank arm	• Vevarm		4	
13	687782-3	1	-	-	-	-	• Bushing	• Bussning		3	
14	687791-4	1	-	-	-	-	• Washer	• Bricka		3	
15	942915-0	1	-	-	-	-	• Safety brace	• Säkringsbygel		2	
16	687784-9	2	-	-	-	-	• Cable	• Lina	LG 370mm	3	
17	1203020-1	1	-	-	-	-	• Cable	• Lina	LG 335mm	2	
18	963104-5	3	-	-	-	-	• Lock nut	• Låsmutter		2	
19	1213987-9	1	-	-	-	-	Seal l.h.	Tätning v		3	
	1312653-7	1	-	-	-	-	Seal r.h.	Tätning h		3	
★ 20	968862-3	2	-	-	-	-	Flange nut	Flänsmutter	(955782)	8	
21	946544-4	6	-	-	-	-	Flange screw	Flänsskruv		2	
22	965175-3	1	-	-	-	-	Flange screw	Flänsskruv		2	
23	1372215-2	1	-	-	-	-	Rubber bushing	Gummibussning		3	
24	1392943-5	1	-	-	-	-	Wiper arm, l.h.	Torkararm, v		1	
	1392944-3	1	-	-	-	-	Wiper arm, r.h.	Torkararm, h		1	
25	1392933-6	1	-	-	-	-	• Cover	• Täckkåpa	BOSCH	3	
	1392918-7	1	-	-	-	-	• Cover	• Täckkåpa	TRICO	3	
26	1372029-7	2	-	-	-	-	Wiper blade	Torkarblad		1	