


© **VOLVO**  
 Genuine Parts  
 PV 360 40092  
 (103:8)



A											REAR WINDOW WASHER		BAKRUTESPOLARE		Group Grupp				
	B															36			
		C															Page Sida		
			D															465	
				E															
Fig	Part No. Artikel nr	Quantity /Antal					P S	Description	Benämning	Notes Anmärkning	S R								
		A	B	C	D	E													
1	1304784-0	1	-	-	-	-		Pump .....	Pump .....		2								
2	1246341-0	4	-	-	-	-		Rivet .....	Nit .....		2								
3	1255919-1	1	-	-	-	-		Bracket .....	Konsol .....	EXC DSL	3								
4	1312044-9	1	-	-	-	-		Bracket .....	Konsol .....	DSL	3								
5	955781-0	2	-	-	-	-		Nut .....	Mutter .....	DSL	2								
6	944385-4	1	-	-	-	-		Clip .....	Clips .....	DSL	3								
7	1304930-9	1	-	-	-	-		T-pipe .....	T-rör .....		3								
8	949931-0	X	-	-	-	-		Rubber hose by the meter .....	Gummislang metervara .....	LG 130mm	2								
9	949931-0	X	-	-	-	-		Rubber hose by the meter .....	Gummislang metervara .....	LG 65mm	2								
10	949931-0	X	-	-	-	-		Rubber hose by the meter .....	Gummislang metervara .....	LG 130mm	2								
11	949931-0	X	-	-	-	-		Rubber hose by the meter .....	Gummislang metervara .....	LG 5100mm	2								
12	949931-0	X	-	-	-	-		Rubber hose by the meter .....	Gummislang metervara .....	LG 1250mm. DSL	2								
13	1304944-0	1	-	-	-	-		Connector .....	Skarvstycke .....	DSL	3								
14	1304460-7	1	-	-	-	-		Delivery valve .....	Tryckventil .....		2								
15	949931-0	X	-	-	-	-		Rubber hose by the meter .....	Gummislang metervara .....	LG 565mm	2								
16	1307159-2	1	-	-	-	-		Nozzle .....	Munstycke .....		2								
☆ 21	1372267-3	1	-	-	-	-		Grommet .....	Genomföring .....		2								