



VOLVO
 Genuine Parts
 PV 320 5127

A							ALTERNATOR WITH MOUNTING PARTS		GENERATOR MED UPPHÄNGNINGSDETALJER		Group
B											Grupp
C											32
D											Page
E							DSL				Sida
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	(1324957)	1	-	-	-	-	SP	Alternator	Generator	55A, -1991	3
		-	-	-	-	-		•SEE 32•327	•SEE 32•327	REPL 1PCS 3544652-5	
	5003802-5	1	-	-	-	-	EU	Alternator, exch	Generator, bytes	55A	3
	3544652-5	1	-	-	-	-		Alternator	Generator	55A, 1992-	3
		-	-	-	-	-		•SEE 32•333	•SEE 32•333		
	5003802-5	1	-	-	-	-	EU	Alternator, exch	Generator, bytes		3
2		1	-	-	-	-		Pulley	Remskiva	SEE 32•327	
3		1	-	-	-	-		Fan	Fläkt	SEE 32•327	
4	1257214-5	1	-	-	-	-		Bracket	Konsol		4
5	1257795-3	1	-	-	-	-		•Bearing	•Lager		2
6	1328850-1	2	-	-	-	-		•Bushing	•Bussning		2
7	949366-9	2	-	-	-	-		Screw	Skruv	(955326)	2
8	941908-6	2	-	-	-	-		Spring washer	Fjäderbricka		2
9	948069-0	1	-	-	-	-		Hexagon screw	Sexkantsskruv	(955298)	2
10	941907-8	1	-	-	-	-		Spring washer	Fjäderbricka		2
11	969225-2	1	-	-	-	-		Flange screw	Flänsskruv		2
12	1257558-5	1	-	-	-	-		Washer	Bricka		2
13	945408-3	1	-	-	-	-		Flange nut	Flänsmutter		2
14	1257339-0	1	-	-	-	-		Tensioning arm	Spännarm		3
15	955303-3	1	-	-	-	-		Screw	Skruv		2
16	941907-8	1	-	-	-	-		Spring washer	Fjäderbricka		2
☆ 17	976944-9	1	-	-	-	-		Washer	Bricka	(960141)	2
18	1257340-8	1	-	-	-	-		Screw	Skruv		5
19	955894-1	1	-	-	-	-		Washer	Bricka		2
20	945408-3	1	-	-	-	-		Flange nut	Flänsmutter		2
21	955781-0	1	-	-	-	-		Nut	Mutter	-1991	2
	945408-3	1	-	-	-	-		Flange nut	Flänsmutter	1992-	2
22	960140-2	1	-	-	-	-		Washer	Bricka	(960139), -1991	2
23	955892-5	1	-	-	-	-		Washer	Bricka	-1991	2
24	1234326-5	1	-	-	-	-		Protecting casing	Skyddskåpa	-1991	2
	3544107-0	1	-	-	-	-		Protecting casing	Skyddskåpa	1992-	2
25		-	-	-	-	-		V-belt	Kilrem	SEE 26•261	2