



VOLVO
Genuine Parts
PV 640 54016

A		1359649, 1359652					SERVO PUMP		SERVOPUMP		Group Grupp
B											64
C											Page Sida
D											749
E							SAGINAW				
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	271311-3	1	-	-	-	-		Locating pin	Styrpinne		4
2	3342655-2	1	-	-	-	-		Spring	Fjäder		3
3	271310-5	1	-	-	-	-		Sleeve	Hylsa		4
4	271312-1	1	-	-	-	-		Sealing ring	Tätningssats		2
5	271314-7	1	-	-	-	-		Retaining ring	Spårring		3
6	1272426-6	1	-	-	-	-		O-ring	O-ring		4
7	271302-2	1	-	-	-	-		Rotor kit	Rotorsats		3
8	271304-8	1	-	-	-	-		Repair kit	Reparationssats		3
9	271305-5	1	-	-	-	-		Repair kit	Reparationssats		2
10	3342651-1	1	-	-	-	-		Sealing kit	Tätningssats		2
11	3342658-6	1	-	-	-	-		Repair kit	Reparationssats		3
12	271313-9	1	-	-	-	-		Repair kit	Reparationssats		3
13	271337-8	1	-	-	-	-		Valve kit	Ventilsats		3