






VOLVO PART

1 101 39085

(111:5)

A B C D E						REPAIR KITS BALL JOINT SPRING SEAT		REPARATIONSSATS KULLED FJÄDERSÄTE		Group Grupp 61	Page Sida 717
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	274117-1	1	-	-	-	-		Ball joint kit	Kulledsats	L.H. W/O P.S	2
	274117-1	1	-	-	-	-		Ball joint kit	Kulledsats	R.H. W/O P.S	2
	274118-9	1	-	-	-	-		Ball joint kit	Kulledsats	L.H. P.S	2
	274119-7	1	-	-	-	-		Ball joint kit	Kulledsats	R.H. P.S	2
2	274100-7	2	-	-	-	-		Repair kit repl. spring strut plate	Reparationssats byte fjäderbenstallrik		1

1



VOLVO
Genuine Parts
PV 610 63411

A B C D E							REPAIR KITS FRONT WHEEL BEARING		REPARATIONSSATS FRAMHJULSLAGER		Group Grupp
											61
											Page Sida
											719
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	271391-5	2	-	-	-	-		Front wheel bearing kit	Framhjulsagersats	(273824)	3