


1



VOLVO PARTS  
1 040 12817

A						HUVUDCYLINDER		HAUPTZYLINDER		Grupp Gruppe	
B										41	
C										Sida Seite	
D										691	
E						1205729				691	
Pos	Artikel nr ArtikeInr.	Antal /Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	1205729-5	1	-	-	-	-		Huvudcylinder .....	Hauptzylinder .....		3
2		1	-	-	-	-	NS	• Hus .....	• Gehäuse .....		
3	1221927-5	1	-	-	-	-		• Fjäder .....	• Feder .....		2
4		1	-	-	-	-	NS	• Kolv .....	• Kolben .....		
5		2	-	-	-	-	KN	• Tättningsring .....	• Dichtring .....		
6	1221929-1	1	-	-	-	-		• Bricka .....	• Scheibe .....		2
7		1	-	-	-	-	KN	• Låsring .....	• Schlossring .....		
8		1	-	-	-	-	KN	• Gummikåpa .....	• Gummimantel .....		
9	1221932-5	1	-	-	-	-		• Kolvstång .....	• Kolbenstange .....		4
10		1	-	-	-	-	NS	• Gummipropp .....	• Gummistöpsel .....		
11	1221933-3	1	-	-	-	-		• Oljebehållare .....	• Ölvorratsbehåller .....		3
12	667360-2	1	-	-	-	-		• Lock .....	• Deckel .....		3
13	667359-4	1	-	-	-	-		• Sil .....	• Sieb .....		3
	273345-9	1	-	-	-	-		Reparationssats .....	Reparatursatz .....	SEE 41-697	2