



VOLVO
 Genuine Parts
 PV 650 47925

A	B	C	D	E	BAKAXELUPPHÄNGNING					HINTERACHSAUFHÄNGUNG					Grupp Gruppe
															65
															Sida Seite
															1009
Pos	Artikel nr Artikelnr.	Antal /Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R				
		A	B	C	D	E									
1	1272361-5	2	-	-	-	-	Bärarm	Querlenker	(1229730)	4					
2	1229714-9	2	-	-	-	-	• Bussning	• Buchse	(1205795)	2					
3	962916-3	2	-	-	-	-	Skruv	Schraube	LG 110 mm	2					
4	945879-5	2	-	-	-	-	Låsmutter	Sicherungsmutter		2					
5		2	-	-	-	-	Bussning	Buchse	SEE 46•869						
6	947564-1	2	-	-	-	-	Skruv	Schraube	LG 115 mm	2					
7	945879-5	2	-	-	-	-	Låsmutter	Sicherungsmutter		2					
8	1273621-1	2	-	-	-	-	Bärstag	Stützstrebe	(1205797)	4					
9	1272603-0	4	-	-	-	-	• Bussning	• Buchse	(1205801)	2					
10	1229370-0	2	-	-	-	-	Konsol	Konsole		4					
11	1247817-8	2	-	-	-	-	Förstärkning	Verstärkung	ALTER	4					
12	962916-3	2	-	-	-	-	Skruv	Schraube	ALTER LG 110 mm	2					
13	955337-1	2	-	-	-	-	Skruv	Schraube	LG 20 mm	2					
14	955897-4	2	-	-	-	-	Bricka	Scheibe		2					
15	947075-8	2	-	-	-	-	Skruv	Schraube	LG 80 mm	2					
16	955349-6	2	-	-	-	-	Skruv	Schraube	LG 75 mm	2					
17	946034-6	2	-	-	-	-	Låsmutter	Sicherungsmutter		4					
18	1330300-3	1	-	-	-	-	Tvärstag	Panhardstange	(1272122)	4					
19	1330973-7	1	-	-	-	-	• Bussning	• Buchse	(1229715)	2					
20	1330427-4	1	-	-	-	-	• Bussning	• Buchse	(675807)	2					
21	1212402-0	1	-	-	-	-	Mutterkåpa	Mutterabdeckkappe		3					
22	955897-4	1	-	-	-	-	Bricka	Scheibe		2					
23	946034-6	1	-	-	-	-	Låsmutter	Sicherungsmutter		4					
24		1	-	-	-	-	Karossbalk	Karosserieträger	SEE 81•1035						
25	955349-6	1	-	-	-	-	Skruv	Schraube	LG 75 mm	2					
26	955897-4	2	-	-	-	-	Bricka	Scheibe		2					
27	946034-6	1	-	-	-	-	Låsmutter	Sicherungsmutter		4					
28	683538-3	1	-	-	-	-	Buffert	Puffer		2					
29	956111-9	1	-	-	-	-	Skruv	Schraube		2					
30	683423-8	2	-	-	-	-	Buffert	Puffer	ALTER 1	1					
	1206265-9	2	-	-	-	-	Buffert	Puffer	ALTER 2	2					
31	946471-0	4	-	-	-	-	Flänsskruv	Flanschschraube		2					