



VOLVO
 Genuine Parts
 PV 370 47687

A	(USA) (CDN)					LEDNINGSMATTA, MOTOR- VÄXELLÅDA		KABELBAUM, MOTOR- GETRIEBE		Grupp	
	B	C	D	E	6CYL					Gruppe	
										37	
										Sida	
										Seite	
										629	
Pos	Artikel nr Artikelnr.	Antal /Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	269967-6	1	1	-	-	-	Ledningsmatta	Kabelbaum	B27A	5	
2	1215191-6	1	1	-	-	-	Motor	Motor	1975 B27 L.H.D	5	
	1215274	1	1	-	-	-	OP Ledningsmatta	Kabelbaum			1975 B27 R.H.D
	269126	1	1	-	-	-	OP Ledningsmatta	Kabelbaum	1975 B27E 264	5	
	269562-5	1	1	-	-	-	Motor	Motor	1976 B27E	5	
	269605	1	1	-	-	-	OP Ledningsmatta	Kabelbaum	1976-1977 B27F	5	
	1269153-1	1	1	-	-	-	Motor	Motor	1978- B27E	5	
3	1234782	1	1	-	-	-	NS Ledningsmatta	Kabelbaum	-1976 B27, M46		
4	243994-1	1	1	-	-	-	Överväxel	Overdrive		4	
5	1307847-2	1	1	-	-	-	• Diod	• Diode	(1234586)	5	
	1308904-0	1	1	-	-	-	Ledningsmatta	Kabelbaum	1976- B27 L.H.D	5	
6	1215055-3	1	1	-	-	-	Startmotor	Anlasser	(1234587)	5	
	1235214-2	1	1	-	-	-	Ledningsmatta	Kabelbaum	1976- B27 R.H.D	5	
	1235323-1	1	1	-	-	-	Bränslepump	Kraftstoffpumpe	-1976 B27E,F.	5	
	948620-0	1	1	-	-	-	Ledningsmatta	Kabelbaum	1977 B27E,F.	5	
7	945970-2	1	1	-	-	-	Bränslepump	Kraftstoffpumpe	(1235057)	5	
8	942605-7	1	1	-	-	-	Ledningsmatta	Kabelbaum	1978- B27E,F	5	
9	948620-0	1	1	-	-	-	Bränslepump	Kraftstoffpumpe		3	
	945970-2	1	1	-	-	-	Stomledning	Masseleitung		2	
	942605-7	1	1	-	-	-	Skruv	Schraube		2	
							Tandbricka	Zahnscheibe		2	