



VOLVO PARTS  
1 030 40251  
(104:3)

A	(USA) (CDN)						LEDNINGSMATTA LUFTKONDITIONERING KABELBAUM KLIMAAANLAGE			Grupp	
	B	C	D	E	Sida					Gruppe	
					633		37				
							Seite				
							633				
Pos	Artikel nr Artikelnr.	Antal /Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
A	B	C	D	E							
1	1234327-3	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	-1977 B20, B21 A.C	5	
							luftkonditionering	Klimaanlage	(1215484)		
	1234092-3	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	1975, B27	5	
							luftkonditionering	Klimaanlage	COMBU, A.C		
	1235191-2	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	1976, B27A, B27F	5	
							luftkonditionering	Klimaanlage	COMBU, A.C		
	1235191-2	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	(1234691)	5	
							luftkonditionering	Klimaanlage	1977, B27F		
	1235191-2	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	(1234691) COMBU, A.C	5	
							luftkonditionering	Klimaanlage	1977, B27A		
1235191-2	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	COMBU, A.C	5		
						luftkonditionering	Klimaanlage	-1977 B27E			
1235026-0	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	COMBU, A.C	5		
						luftkonditionering	Klimaanlage	EXC (AUS)			
1235346-2	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	(1234691)	5		
						luftkonditionering	Klimaanlage	-1977 B27			
1235347-0	1	1	-	-	-	Ledningsmatta .....	Kabelbaum .....	COMBU, A.C	5		
						luftkonditionering	Klimaanlage	264 CH 38267-			
2	1212727-0	1	1	-	-	-	Elledning .....	El leitung .....	265 CH 9335-	5	
							Strömställare	Schalter	1978- 240		
							Dimbaklykta	Nebelschlussleuchte	COMBU, A.C		
							luftkonditionering	Klimaanlage	1978- 260		
									COMBU, A.C		