



VOLVO PARTS
1 030 13035

A	241735					GENERATOR		LICHTMASCHINE		Grupp Gruppe	
	B	C	D	E	P S	Benämning	Bezeichnung	Anmärkning Anmerkung	32		
									Sida Seite		
									503		
Pos	Artikel nr Artikelnr.	Antal /Anzahl								S R	
		A	B	C	D	E					
1	241735-0	1	-	-	-	-	Generator	Lichtmaschine	1)		3
2	243986-7	1	-	-	-	-	• Stator	• Ständer	(243288)		4
3	243628-5	1	-	-	-	-	• Hus främre	• Gehäuse vordere			2
4	243629-3	1	-	-	-	-	• Rotor	• Rotor			3
5	241681-6	1	-	-	-	-	• Släpning	• Schleifring			2
6	181800-4	1	-	-	-	-	• Kullager	• Kugellager			2
7	181798-0	1	-	-	-	-	• Kullager	• Kugellager			2
8	241682-4	1	-	-	-	-	• Hållare	• Halter			2
9		1	-	-	-	-	NS • Hus bakre	• Gehäuse hintere	(243755)		
10	241684-0	1	-	-	-	-	• Hållare	• Halter			2
11	244456-0	1	-	-	-	-	••• Elborstsats	••• Kohleburstsats	(243990)		2
12	241686-5	2	-	-	-	-	••• Fjäder	••• Feder			2
13	241687-3	3	-	-	-	-	••• Diod	••• Diode			2
14	243756-4	1	-	-	-	-	• Kylplatta	• Kuhlplatte			2
15		1	-	-	-	-	NS • Kylplatta	••• Kuhlplatte	(243757)		
16	244311-7	3	-	-	-	-	••• Diod	••• Diode	(241690)		2
17	244454-5	1	-	-	-	-	••• Diodplatta	••• Diodenplatte	(243993)		3
18	243994-1	3	-	-	-	-	••• Diod	••• Diode	(243760)		4
19	243032-0	1	-	-	-	-	• Skruv	• Schraube			3
20	955919-6	2	-	-	-	-	NS • Skruv	• Schraube	(243630)		
21	955892-5	3	-	-	-	-	• Fjäderbricka	• Federscheibe			2
22	241695-6	1	-	-	-	-	• Bricka	• Scheibe			2
23	243456-1	1	-	-	-	-	• Kåpa	• Haube			4
24	1324620-2	1	-	-	-	-	• Remskiva	• Riemenscheibe			2
25	273538-9	1	-	-	-	-	• Fläkt	• Gebläse	(243457)		2
26	273539-7	1	-	-	-	-	Reparationssats	Reparatursatz			2
							Reparationssats	Reparatursatz			2

1) Serviceskylten märkt 1. / Serviceschild, mit Kennzeichnung 1.