



(111:1) VOLVO PARTS 1 101 20883

A							REPARATIONSSATS		REPARATURSÄTZE		Grupp	
B							KYLSYSTEM		KÜHLANLAGE		Gruppe	
C											26	
D											Sida	
E											431	
Pos	Artikel nr Artikelnr.	Antal /Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R	
		A	B	C	D	E						
1	270680-2	1	-	-	-	-	Vattenpumpsats	Wasserpumpsatz	(275616) B20	2		
	270681-0	1	-	-	-	-	Vattenpumpsats	Wasserpumpsatz	(275619) B19, B21			
2	273342-6	1	-	-	-	-	Termostatsats	Termostatsatz	B20, 82°C-180°F	1		
	273458-0	1	-	-	-	-	Termostatsats	Termostatsatz	B20, 87°C-189°F	1		
	273277-4	1	-	-	-	-	Termostatsats	Termostatsatz	B20, 92°C-189°F	1		
	273459-8	1	-	-	-	-	Termostatsats	Termostatsatz	B19, B21 87°C-189°F	1		
	273307-9	1	-	-	-	-	Termostatsats	Termostatsatz	B19, B21 92°C-197°F	1		
	273480-4	1	-	-	-	-	Termostatsats	Termostatsatz	B27, 87°C-189°F	1		
	273364-0	1	-	-	-	-	Termostatsats	Termostatsatz	B27, 92°C-197°F	1		