



VOLVO
Genuine Parts
PV 520 47837

A	B	C	D	E	REPARATIONSSATS HUVUDCYLINDER. SERVOCYLINDER VARNINGSVENTIL		REPARATURSÄTZE HAUPTZYLINDER, SERVOZYLINDER WARNVENTIL		Grupp Gruppe		
									52		
									Sida Seite		
									935		
Pos	Artikel nr Artikelnr.	Antal /Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	271131-5	1	-	-	-	-	Reparationssats	Reparatursatz	(272602)	1	
2	272595-0	1	-	-	-	-	Reparationssats	Reparatursatz		1	
	272596-8	1	-	-	-	-	Reparationssats	Reparatursatz		1	
3	270596-0	1	-	-	-	-	Ventilsats	Ventilsatz		2	
4	272702-2	1	-	-	-	-	Kontaktsats	Kontaktsatz		1	