



VOLVO PARTS
 1022 16667

A	B	C	D	E	LUBRICATING SYSTEM		SMÖRJSYSTEM		Group Grupp		
									22		
									Page Sida		
							B200		139		
Fig Pos	Part no. Artikel nr.	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	1276476-7	1	-	-	-	-	NS	Oil pump	Oljepump		2
2		-	-	-	-	-		• Housing	• Hus		8
3	463963-9	1	-	-	-	-		• Valve	• Spjäll		
4	1276171-4	1	-	-	-	-		• Shaft	• Axel		3
5	430114-9	1	-	-	-	-		• Gear	• Växel		
6	1332053-6	1	-	-	-	-		• Piston	• Kolv	(12195327)	3
7	1219536-8	1	-	-	-	-		• Spring	• Fjäder		3
8	1219666-3	1	-	-	-	-		• Dowel pin	• Styrpinne		2
9	1276478-3	1	-	-	-	-		• Lower section	• Underdel		3
10	942247-8	4	-	-	-	-		• Screw	• Skruv		
11	941906-0	4	-	-	-	-		• Resilient washer	• Fjädrande bricka		
12	955296-9	2	-	-	-	-		Screw	Skruv		
13	941907-8	2	-	-	-	-		Resilient washer	Fjädrande bricka		
14	463365-7	1	-	-	-	-		Shaft	Axel		
15	418360-4	2	-	-	-	-	IK	Rubber ring	Gummiring		
16	1276106-0	1	-	-	-	-		Delivery pipe	Tryckrör		3
17	3294431-6	1	-	-	-	-		Sump	Oljesump		4
18	11998-2	1	-	-	-	-	IK	• Gasket	• Packning		
19	3224662-1	1	-	-	-	-		• Plug	• Propp		1
20	946173-2	18	-	-	-	-		Screw	Skruv		
21	1378864-1	1	-	-	-	-	IK	Gasket	Packning	(4635876)	1
22	1266286-2	1	-	-	-	-	IK	Oil filter	Oljefilter		1
23	418440-4	1	-	-	-	-		Nipple	Nippel		
24	955295-1	1	-	-	-	-		Screw	Skruv		
25	3212285-5	1	-	-	-	-		Pipe	Rör	(32963811)	3
26	3296495-9	1	-	-	-	-		O-ring	O-ring		2
27	1276369-4	1	-	-	-	-		Dipstick	Mätsticka		3
28	3296494-2	1	-	-	-	-		O-ring	O-ring		2