




VOLVO
Genuine Parts
PV360 45528

A						BAKRUTETORKARE		HECKSCHEIBENWISCHER		Grupp Gruppe	
B										36	
C										Sida Seite	
D										701	
E											
Pos	Artikel nr Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	1358011-3	1	-	-	-	-		Motor	Motor		2
2	965175-3	3	-	-	-	-		Flänsskruv	Flanschschraube	M6x12mm	2
3	1358012-1	1	-	-	-	-		Länksystem med vevarm	Gelenksystem mit Kurbelarm ..		3
4	955781-0	1	-	-	-	-		Mutter	Mutter	M6x5mm	2
5	955900-6	1	-	-	-	-		Bricka	Scheibe		2
6	190734-4	1	-	-	-	-		Mutter	Mutter	M16x5mm	2
7	1342040-1	1	-	-	-	-		Tätning	Dichtung		3
8	1392934-4	1	-	-	-	-		Torkararm	Wischerarm		2
9	1392935-1	1	-	-	-	-		• Täckkåpa	• Abdeckhaube		2
10	271334-5	1	-	-	-	-		Torkarbladsats	Wischerblattsatz	(3518841)	1
11	955781-0	1	-	-	-	-		Mutter	Mutter	M6x5mm	2