






VOLVO
Genuine Parts
PV 260 44094

A						REPARATIONSSATS		REPARATURSÄTZE		Grupp Gruppe		
B						KYLSYSTEM		KÜHLANLAGE			26	
C												Sida Seite
D												
E										537		
Pos	Artikel nr Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R	
		A	B	C	D	E						
1	270558-0	1	-	-	-	-		Reparationssats	Reparatursatz	D24T, D24TIC	5	
2	273459-8	1	-	-	-	-		Termostatsats	Termostatsatz	B200,B230 87°C-189°F	1	
	273307-9	1	-	-	-	-		Termostatsats	Termostatsatz	B200,B230 92°C-197°F	1	
	273320-2	1	-	-	-	-		Termostatsats	Termostatsatz	B28 82°C-180°F	1	
	273480-4	1	-	-	-	-		Termostatsats	Termostatsatz	B28,B280 87°C-189°F	1	
	273364-0	1	-	-	-	-		Termostatsats	Termostatsatz	B28 92°C-197°F	1	
	273728-6	1	-	-	-	-		Termostatsats	Termostatsatz	D24,D24T,D24TIC 87°C-189°F	1	
3	(271275)	1	-	-	-	-	SP	Vattenpumpsats	Wasserpumpensatz	(270559) B200, B230	2	