




VOLVO
Genuine Parts
PV 270 43123

A						KONSTANTFARTHÅLLARE		TEMPOMAT		Grupp Gruppe	
B										27	
C										Sida Seite	
D										581	
E								B280E, B280F			
Pos	Artikel nr Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	3501472-9	1	-	-	-	-		Styrenhet	Steuergerät	(1273225)	4
2	1273226-9	1	-	-	-	-		Vakuumpförstärkare	Unterdruckverstärker		4
3	1273227-7	1	-	-	-	-		Servo enhet	Servoaggregat		4
4	1367159-9	1	-	-	-	-		Avluftningsventil	Entlüftungsventil		3
5	1332203-7	1	-	-	-	-		Konsol	Konsole		5
6	972079-8	2	-	-	-	-		Sextandhålskruv	Sechszahn-hohlschraube	(968464)	2
7		2	-	-	-	-		Skruv	Schraube		
8	1271216-2	1	-	-	-	-		Konsol	Konsole		5
9	955271-2	2	-	-	-	-		Skruv	Schraube	(955270)	2
10	945408-3	1	-	-	-	-		Flänsmutter	Bundmutter		2
11	1273239-2	1	-	-	-	-		Nippel	Nippel		3
12	976735-1	X	-	-	-	-		Slang	Schlauch	(1336649) LG 690 mm	2
13	976735-1	X	-	-	-	-		Slang	Schlauch	(1336649) LG 270 mm	2
14	976735-1	X	-	-	-	-		Slang	Schlauch	(1336649) LG 40 mm	2
15	976735-1	X	-	-	-	-		Slang	Schlauch	(1336649) LG 1030 mm L.H.D	2
	976735-1	X	-	-	-	-		Slang	Schlauch	(1336649) LG 1590 mm R.H.D	2
16	976735-1	X	-	-	-	-		Slang	Schlauch	(1336649) LG 110 mm	2
17	1273229-3	1	-	-	-	-		Konsol	Konsole		5
18	190665-0	3	-	-	-	-		Skruv	Schraube		2
19	969476-1	3	-	-	-	-		Sextandhålskruv	Sechszahn-hohlschraube	(955141)	2
20	1389194-0	1	-	-	-	-		Konsol	Konsole	(1357629)	5
21	941806-2	X	-	-	-	-		Blindnit	Blindniet		2
22	1359139-1	1	-	-	-	-		Justermutter	Stellmutter		2
23	947515-3	1	-	-	-	-		Spärryttare	Nutenläufer		2
24	1389353-2	1	-	-	-	-		Gasreglagewire	Gasregelzug		3
25		1	-	-	-	-		Reglagerulle	Seilrolle	SEE 27 • 559	
26	941806-2	2	-	-	-	-		Blindnit	Blindniet		2
27	1367312-4	1	-	-	-	-		Fjäder	Feder		
28	948211-8	2	-	-	-	-		Bandklamma	Bandklammer		2
	3501276-4	1	-	-	-	-		Konstantfarthållarsats	Tempomatsatz	SEE 27 • 587	3
	3501283-0	1	-	-	-	-		Kompletteringssats	Ergänzungssatz	SEE 27 • 587	3
	3501280-6	1	-	-	-	-		Kompletteringssats	Ergänzungssatz	R.H.D	
										SEE 27 • 587	3