




VOLVO PARTS
1 060 39059
(107:2)

A						PUMP SERVOSTYRNING		PUMPE SERVOLENKUNG		Grupp Gruppe	
B										64	
C										Sida Seite	
D										1209	
E											
Pos	Artikel nr Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1		1	-	-	-	-		Styrväxel	Lenkgetriebe	SEE 64 • 1195	
2	1359116-9	1	-	-	-	-		Servopump	Servoölpumpe		5
		-	-	-	-	-		•SEE 64 • 1229	•SEE 64 • 1229		
3	464276-5	1	-	-	-	-		Konsol	Konsole		4
4	940142-3	1	-	-	-	-		Skruv	Schraube	M8X30	2
5	945444-8	2	-	-	-	-		Flänsskruv	Flanschschraube	(955297) M8X25	2
6	970947-8	2	-	-	-	-		Skruv	Schraube	(955317) M10X25	2
7	464277-3	1	-	-	-	-		Spännjörn	Spanneisen		5
8	464322-7	1	-	-	-	-		Distansbricka	Abstandscheibe		4
9	960148-5	1	-	-	-	-		Bricka	Scheibe		2
10	970947-8	1	-	-	-	-		Skruv	Schraube	(970947) M10X25	2
11	948069-0	1	-	-	-	-		Sexkantsskruv	Sechskantschraube	(955298) M8X40	2
12	955782-8	1	-	-	-	-		Mutter	Mutter		2
13	1219961-8	1	-	-	-	-		Remskiva	Riemenscheibe		4
14	944926-5	4	-	-	-	-		Flänsskruv	Flanschschraube		2
15	973542-4	1	-	-	-	-		Kilrem servopump-vevaxel	Keilriemen	38X988	1
									Servopumpe-Kurbelwelle		
16	1387923-4	1	-	-	-	-		Tryckslang	Druckschlauch	L.H.D	3
	1387669-3	1	-	-	-	-		Tryckslang	Druckschlauch	(1329843) R.H.D	3
17	948490-8	1	-	-	-	-		Hålskruv	Hohlschraube		2
18	11996-6	2	-	-	-	-		Packning	Dichtung		1
19	968179-2	1	-	-	-	-		Hålskruv	Hohlschraube		2
20	18671-8	2	-	-	-	-		Packning	Dichtung		2
21	1228399-0	X	-	-	-	-		Returslang	Rucklaufschlauch	LG 420 L.H.D	2
	1228399-0	X	-	-	-	-		Returslang	Rucklaufschlauch	LG 820 R.H.D	2
22	3516385-6	1	-	-	-	-		Nippel	Nippel	(1273376) L.H.D	3
	1273377-0	1	-	-	-	-		Nippel	Nippel	R.H.D	3
23	974678-5	1	-	-	-	-		Hålskruv	Hohlschraube	(941686)	2
24	11996-6	2	-	-	-	-		Packning	Dichtung		1
25	943471-3	2	-	-	-	-		Slangklamma	Schlauchschelle		2
26	948211-8	1	-	-	-	-		Bandklamma	Bandklammer		2