




VOLVO
Genuine Parts
PV 640 47143

A	L.H.D					PUMP SERVOSTYRNING		PUMPE SERVOLENKUNG		Grupp Gruppe	
B	R.H.D									64	
C										Sida	
D										Seite	
E								B280		1211	
Pos	Artikel nr Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1		1	1	-	-	-		Styrväxel	Lenkgetriebe	SEE 64 • 1195	
2	1387724-6	1	1	-	-	-		Servopump	Servoölpumpe		5
		-	-	-	-	-		•SEE 64 • 1229	•SEE 64 • 1229		
3	464276-5	1	1	-	-	-		Konsol	Konsole		4
4	946671-5	1	1	-	-	-		Flänsskruv	Flanschschraube	M8X30	2
5	945444-8	2	2	-	-	-		Flänsskruv	Flanschschraube	M8X25	2
6	946329-0	2	2	-	-	-		Flänsskruv	Flanschschraube	M10X25	2
7	1389221-1	1	1	-	-	-		Fästarm	Befestigungsarm		5
8	946471-0	2	2	-	-	-		Flänsskruv	Flanschschraube	M10X16	2
9	1389219-5	1	1	-	-	-		Spännarm	Spannhebel		5
10		1	1	-	-	-	NS	• Ställskruv	• Stellschraube		
11		1	1	-	-	-	NS	• Låsskruv	• Sicherungsschraube		
12	948645-7	1	1	-	-	-		Flänslåsmutter	Flanschverschlussmutter	M8	2
13	970551-8	1	1	-	-	-		Elledning	El leitung	(955221) M10X45	2
14	971095-5	1	1	-	-	-		Flänsmutter	Bundmutter	(945409) M10	3
15	1219961-8	1	1	-	-	-		Remskiva	Riemenscheibe		4
16	944926-5	4	4	-	-	-		Flänsskruv	Flanschschraube	M8X14	2
17	973542-4	1	1	-	-	-		Kilrem	Keilriemen		1
18	1387923-4	1	-	-	-	-		Tryckslang	Druckschlauch		3
	1387669-3	-	1	-	-	-		Tryckslang	Druckschlauch	(1329843)	3
19	948490-8	1	1	-	-	-		Hålskruv	Hohlschraube		2
20	11996-6	2	2	-	-	-		Packning	Dichtung		1
21	968179-2	1	1	-	-	-		Hålskruv	Hohlschraube		2
22	18838-3	2	2	-	-	-		Packning	Dichtung	(947621)	2
23	1228399-0	X	X	-	-	-		Returslang	Rücklaufschlauch	LG 780 mm	2
24	3516385-6	1	-	-	-	-		Nippel	Nippel	(1273376)	3
	1273377-0	-	1	-	-	-		Nippel	Nippel		3
25	974678-5	1	1	-	-	-		Hålskruv	Hohlschraube	(941686)	2
26	11996-6	2	2	-	-	-		Packning	Dichtung		1
27	967919-2	2	2	-	-	-		Slangklamma	Schlauchschelle		2
28	948211-8	1	1	-	-	-		Bandklamma	Bandklammer		2