




VOLVO PARTS
+ 980- 29016
407-6+

A						REPARATIONSDELAR, KAROSSIDA		REPARATURTEILE, KAROSSERIESEITE		Grupp Gruppe	
										81	
										Sida Seite	
										953	
Pos	Artikelnummer -Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	(1355065)	1	-	-	-	-	SP	Karossida, v	Karosseriewand, l	REPL 1PCS 1380002-4	
☆	(1380002)	1	-	-	-	-	SP	Karossida, v	Karosseriewand, l	REPL 1PCS 3526920-8	6
☆	(3526920)	1	-	-	-	-	SP	Karossida, v	Karosseriewand, l	REPL 1PCS 3526088-4	
☆	(3526088)	1	-	-	-	-	SP	Karossida, v	Karosseriewand, l	REPL 1PCS 3528861-2	6
☆	3528861-2	1	-	-	-	-		Karossida, v	Karosseriewand, l		5
	(1355066)	1	-	-	-	-	SP	Karossida, h	Karosseriewand, r	REPL 1PCS 1380003-2	
☆	(1380003)	1	-	-	-	-	SP	Karossida, h	Karosseriewand, r	REPL 1PCS 3526921-6	6
☆	(3526921)	1	-	-	-	-	SP	Karossida, h	Karosseriewand, r	REPL 1PCS 3526089-2	6
☆	(3526089)	1	-	-	-	-	SP	Karossida, h	Karosseriewand, r	REPL 1PCS 3528862-0	5
☆	3528862-0	1	-	-	-	-		Karossida, h	Karosseriewand, r		5
2	1380015-6	1	-	-	-	-		• Torpedsida, v	• Seitenwandteil, l	(1316640)	5
(	1380016-4	1	-	-	-	-		• Torpedsida, h	• Seitenwandteil, r	(1355713)	5
3	1380017-2	1	-	-	-	-		• B-stolpe, v	• B-säule, l	(1334399)	3
	1380018-0	1	-	-	-	-		• B-stolpe, h	• B-säule, r	(1334400)	3
4	1380019-8	1	-	-	-	-		• Bakstolpe, v	• Hecksäule, l	(1316644)	4
	1380020-6	1	-	-	-	-		• Bakstolpe, h	• Hecksäule, r	(1316645)	4
5	1380021-4	1	-	-	-	-		• Taksvällare, v	• Dachschweller, l	(1334696)	4
(	1380022-2	1	-	-	-	-		• Taksvällare, h	• Dachschweller, r	(1334697)	4
6	1380023-0	1	-	-	-	-		• Bottensvällare, v	• Bodenschweller, l	(1316648)	3
	1380024-8	1	-	-	-	-		• Bottensvällare, h	• Bodenschweller, r	(1316649)	3
7	1355885-3	1	-	-	-	-		• Skärmdel, v	• Kotflügelteil, l	(1316636)	2
	1355886-1	1	-	-	-	-		• Skärmdel, h	• Kotflügelteil, r	(1316637)	2
☆	3526117-1	1	-	-	-	-		• Bakskärm, v	• Hinterkotflügel, l	(1380133)(1355887)	2
☆	3526118-9	1	-	-	-	-		• Bakskärm, h	• Hinterkotflügel, r	(1380134)(1355888)	2