





VOLVO
Genuine Parts
PV 230 43687

A	B23ET					ÖVERSTRÖMNINGSVENTIL		ÜBERSTRÖMVENTIL		Grupp	
B	B23FT									23	
C										Sida	
D										Seite	
E						B23ET,B23FT				247	
Pos	Artikelnummer Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1	1336478-1	1	1	-	-	-		Konsol	Konsole		4
2	959220-5	5	5	-	-	-		Insexskruv	Inbusschraube		2
3	1389225-2	1	1	-	-	-		Ventil	Ventil	(1336380)	3
4	3501515-5	1	1	-	-	-	IK	Packning	Dichtung	(1336482)	1
5	3501516-3	1	-	-	-	-	IK	Packning	Dichtung	1) (1336483)	1
	3501515-5	1	1	-	-	-	IK	Packning	Dichtung	2) (1336482)	1
6	(1336481)	1	-	-	-	-	SP	Fläns	Flansch	1) REPL 1PCS 1346530-7, 1PCS 1336482-3	
	1346530-7	1	1	-	-	-		Fläns	Flansch	2)	3
7	943469-7	2	2	-	-	-		Slangklamma	Schlauchschelle	(946709)	2
8	976735-1	X	X	-	-	-		Slang	Schlauch	LG 400 mm (1336649)	2
9	1346748-5	4	4	-	-	-		Ventil	Ventil		3
10	1346748-5	1	1	-	-	-		Ventil	Ventil	(1336392)	3
11	976735-1	X	X	-	-	-		Slang	Schlauch	LG 140 mm (1336649)	2
12		-	-	-	-	-		Slang	Schlauch		
		1	-	-	-	-		Laddluftkylare	Ladeluftkühler		
		-	1	-	-	-		• SEE 26 • 385/A	• SEE 26 • 385/A		
		-	-	-	-	-		• SEE 26 • 385/B	• SEE 26 • 385/B		
13		-	-	-	-	-		Slang	Schlauch		
		1	-	-	-	-		• SEE 23 • 285/A	• SEE 23 • 285/A		
		-	1	-	-	-		• SEE 23 • 285/B	• SEE 23 • 285/B		

1) B23ET (499892) ENG -530

2) B23ET (499892) ENG 531-. B23FT