


1



VOLVO PARTS
1 022 34510
(102:1)

A	B23ET					LADDLUFTKYLNING		LADELUFTKÜHLUNG		Grupp Gruppe	
	B23FT									26	
										Sida Seite	
										385	
								B2 3 ET, B2 3 FT			
Pos	Artikelnummer Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R
		A	B	C	D	E					
1		1	-	-	-	-	NS	Laddluftkylning	Ladeluftkühlung		
		-	1	-	-	-	NS	Laddluftkylning	Ladeluftkühlung		
2	1317319-0	1	1	-	-	-		• Laddluftkylare	• Ladeluftkühler		3
3	1332139-3	1	1	-	-	-		• • Plugg	• • Stopfen		2
4	949657-1	1	1	-	-	-	IK	• • O-ring	• • O-ring		2
5	1276963-4	1	1	-	-	-		• Slang	• Schlauch		3
6	1336438-5	1	1	-	-	-		• Rör	• Rohrleitung		3
7	1336815-4	1	-	-	-	-		• Slang	• Schlauch	(1332551)	3
	1336815-4	-	1	-	-	-		• Slang	• Schlauch		3
8	1336814-7	1	1	-	-	-		• Slang	• Schlauch	(1346235)	3
9	1336676-0	1	-	-	-	-		• Rör	• Rohrleitung		3
	1336888-1	-	1	-	-	-		• Rör	• Rohrleitung		3
10	1336813-9	1	1	-	-	-		• Slang	• Schlauch	(1317370)	3
11	943479-6	2	2	-	-	-		• Slangklamma	• Schlauchschelle	(966656)	2
12	967765-9	1	1	-	-	-		• Slangklamma	• Schlauchschelle		2
13	967764-2	5	5	-	-	-		• Slangklamma	• Schlauchschelle		3
14	1336977-2	1	1	-	-	-		• Slang	• Schlauch	(1336712)	3
15	943475-4	2	2	-	-	-		• Slangklamma	• Schlauchschelle		2
16	1357202-9	12	12	-	-	-		• Hållare	• Halter		2
17	1357202-9	4	4	-	-	-		• Hållare	• Halter		2
18		2	2	-	-	-		• Konsol	• Konsole		
								• • SEE 26 • 369/B	• • SEE 26 • 369/B		
19		2	2	-	-	-		• Gummikudde	• Gummikissen		
								• • SEE 26 • 369/B	• • SEE 26 • 369/B		