






A							REPARATIONSSATS HUVUDCYLINDER VARNINGSVENTIL		REPARATURSÄTZE HAUPTZYLINDER WARNVENTIL		Grupp Gruppe	
											52	
											Sida Seite	
											851	
Pos	Artikelnummer Artikelnr.	Antal / Anzahl					P S	Benämning	Bezeichnung	Anmärkning Anmerkung	S R	
		A	B	C	D	E						
1	272795-6	1	-	-	-	-		Reparationssats	Reparatursatz			1
2	272912-7	1	-	-	-	-		Reparationssats	Reparatursatz			1
3	272702-2	1	-	-	-	-		Kontaktsats	Kontaktsatz			1
4	1359024	1	-	-	-	-	NS	Servicesats	Servicesatz			