





VOLVO
Genuine Parts
PV 360 61460

A		SWF					WINDSCREEN WIPERS		VINDRUTETORKARE		Group Grupp	
B											36	
C											Page Sida	
D											607	
E												
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R	
		A	B	C	D	E						
1		1	-	-	-	-	NS	Windscreen wiper complete ...	Vindrutetorkare komplett	1)		
2	3518119-7	1	-	-	-	-		•Transmission	•Transmission		4	
3	1369107-6	1	-	-	-	-		Bearing	Lager		4	
4	1358181-4	2	-	-	-	-		•Crank arm	•Vevarm		3	
5	1304975-4	2	-	-	-	-		•Bushing	•Bussning		3	
6	1369110-0	1	-	-	-	-		•Cover	•Kåpa		3	
7	1369111-8	1	-	-	-	-		•Companion flange	•Medbringare		3	
8	963104-5	1	-	-	-	-		•Cable	•Lina		3	
9	3518187-4	1	-	-	-	-		•Flange lock nut	•Flänslåsmutter		2	
10	3518188-2	1	-	-	-	-		•Link arm	•Länkarm		3	
11	3518120-5	1	-	-	-	-		•Sealing bellows	•Tätningsbälg		3	
12	1369106-8	1	-	-	-	-		•Motor	•Motor		2	
13	1259831-4	1	-	-	-	-		•Seal	•Tätning		4	
14	955892-5	3	-	-	-	-		•Pin housing	•Stiftisolator		2	
15	955269-6	3	-	-	-	-		•Washer	•Bricka		2	
16	945408-3	1	-	-	-	-		•Screw	•Skruv		2	
17	948211-8	1	-	-	-	-		•Flange nut	•Flänsmutter		2	
18	965175-3	1	-	-	-	-		•Strip clamp	•Bandklamma		2	
19	1342880-0	1	-	-	-	-		Flange screw	Flänsskruv	(967552)	2	
20	94081-7	1	-	-	-	-		Mudflap	Stänkskydd		4	
21	1392060-8	1	-	-	-	-		Plug	Plugg		3	
22	945444-8	4	-	-	-	-		Spacer sleeve	Distanshylsa		3	
23	945444-8	2	-	-	-	-		Flange screw	Flänsskruv	(967573)	2	
24	1258623-6	2	-	-	-	-		Seal	Tätning		3	
25	1342289-4	1	-	-	-	-		Support	Stöd		3	
26	1392917-9	2	-	-	-	-		Wiper arm	Torkararm	ALTER 1	2	
27	1392918-7	1	-	-	-	-		•Cover	•Täckkåpa		3	
28	3538316-5	2	-	-	-	-		Wiper arm	Torkararm	ALTER 2. (1392931)	2	
29	3538351-2	1	-	-	-	-		•Cover	•Täckkåpa		3	
30	955782-8	2	-	-	-	-		Nut	Mutter		2	
31	6846246-4	2	-	-	-	-		Wiper blade	Torkarblad	ALTER 1 (1392920)	1	
	1392518-5	2	-	-	-	-		Wiper blade	Torkarblad	ALTER 2	1	

1) 4DRS CH APP 254244-. 5DRS CH APP 152662-.