




VOLVO
Genuine Parts
PV 610 55853

A						REPAIR KITS BALL JOINT					REPARATIONSSATS KULLED					Group Grupp	
B																61	
C											Page Sida						
D											1107						
E																	
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R						
		A	B	C	D	E											
1	270477-3	2	-	-	-	-		Ball joint kit	Kulledsats			2					