

This diagram illustrates the exploded view of a ZF rear axle assembly. The components are numbered 1 through 5:

- 1:** A small bolt or screw used for the axle housing.
- 2:** A long axle shaft.
- 3:** A large, multi-lobed differential housing component.
- 4:** A small washer or spacer.
- 5:** A large nut or cap nut used to secure the axle housing.

The diagram shows the relative positions of these parts, including the axle housing, differential housing, and the axle shaft assembly.

[illegible]

VOLVO
Genuine Parts
PV 640 54011

A	1387286	SERVO PUMP					SERVOPUMP					Group Grupp	
B	1359649, 1359652											64	
C												Page	
D												Sida	
E												1127	
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R		
		A	B	C	D	E							
1	271320-4	1	-	-	-	-		Screw	Skruv		3		
2	271318-8	1	-	-	-	-		Shaft	Axel		3		
3	271319-6	1	-	-	-	-		Retaining ring	Spårring		3		
4	271317-0	1	-	-	-	-		Sealing ring	Tätningsring		2		
5	1387621-4	1	-	-	-	-		Fitting	Rörkoppling		4		
6	271315-4	1	-	-	-	-		Nipple	Nippel		4		
7	957181-1	1	-	-	-	-		Gasket	Packning		2		
8	271311-3	-	1	-	-	-		Locating pin	Styrpinne		4		
9	3342655-2	-	1	-	-	-		Spring	Fjäder		3		
10	271310-5	-	1	-	-	-		Sleeve	Hylsa		4		
11	271312-1	-	1	-	-	-		Sealing ring	Tätningsring		2		
12	271314-7	-	1	-	-	-		Retaining ring	Spårring		3		
13	1272426-6	-	1	-	-	-		O-ring	O-ring		4		
14	271301-4	1	-	-	-	-		Sealing kit	Tätningssats		2		
15	271302-2	-	1	-	-	-		Rotor kit	Rotorsats		3		
16	271304-8	-	1	-	-	-		Repair kit	Reparationssats		3		
17	271305-5	-	1	-	-	-		Repair kit	Reparationssats		2		
18	3342651-1	-	1	-	-	-		Sealing kit	Tätningssats		2		
19	3342658-6	-	1	-	-	-		Repair kit	Reparationssats		3		
20	271313-9	-	1	-	-	-		Repair kit	Reparationssats		3		
21	271337-8	-	1	-	-	-		Valve kit	Ventilsats		3		