




VOLVO PARTS
1 080 29016
(107:6)

A B C D E							REPAIR PARTS, BODY SIDE		REPARATIONSDELAR, KAROSSIDA		Group Grupp
											81
											Page Sida
											705
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
☆ 1	3526920-8	1	-	-	-	-		Body side, l.h.	Karossida, v		5
☆ 2	3526921-6	1	-	-	-	-		Body side, r.h.	Karossida, h		5
2	1380015-6	1	-	-	-	-		• Cowl side, l.h.	• Torpedsida, v	1)	5
	1380016-4	1	-	-	-	-		• Cowl side, r.h.	• Torpedsida, h	1)	5
3	1380017-2	1	-	-	-	-		• B-pillar, l.h.	• B-stolpe, v	1)	3
	1380018-0	1	-	-	-	-		• B-pillar, r.h.	• B-stolpe, h	1)	3
4	1380019-8	1	-	-	-	-		• Rear pillar, l.h.	• Bakstolpe, v	1)	4
	1380020-6	1	-	-	-	-		• Rear pillar, r.h.	• Bakstolpe, h	1)	4
5	1380021-4	1	-	-	-	-		• Cant rail, l.h.	• Taksvällare, v	1)	4
	1380022-2	1	-	-	-	-		• Cant rail, r.h.	• Taksvällare, h	1)	4
6	1380023-0	1	-	-	-	-		• Bottom rail, l.h.	• Bottensvällare, v	1)	3
	1380024-8	1	-	-	-	-		• Bottom rail, r.h.	• Bottensvällare, h	1)	3
7	1355885-3	1	-	-	-	-		Mudguard repair part, l.h.	Skärmdel, v	1)	2
	1355886-1	1	-	-	-	-		Mudguard repair part, r.h.	Skärmdel, h	1)	2
8	3526117-1	1	-	-	-	-		Rear mudguard l.h.	Bakskärm v	1) 4DRS	2
	3526118-9	1	-	-	-	-		Rear mudguard r.h.	Bakskärm h	1) 4DRS	2

1) Service version. / Serviceutförande.