





VOLVO
Genuine Parts
PV360 45528

A						REAR WINDOW WIPER		BAKRUTETORKARE		Group Grupp	
B										36	
C										Page	
D										Sida	
E										345	
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	1358011-3	1	-	-	-	-		Motor	Motor		2
2	965175-3	3	-	-	-	-		Flange screw	Flänsskruv		2
3	1358012-1	1	-	-	-	-		Linkage with crank arm	Länksystem med vevarm		3
4	955781-0	1	-	-	-	-		Nut	Mutter		2
5	955900-6	1	-	-	-	-		Washer	Bricka		2
6	190734-4	1	-	-	-	-		Nut	Mutter		2
7	1342040-1	1	-	-	-	-		Seal	Tätning		3
8	1392934-4	1	-	-	-	-		Wiper arm	Torkarm		2
9	1392935-1	1	-	-	-	-		• Cover	• Täckkåpa		2
10	3518841-6	1	-	-	-	-		Wiper blade	Torkarblad		1
11	955781-0	1	-	-	-	-		Nut	Mutter		2



VOLVO
Genuine Parts
PV360 45533

A							REAR WINDOW WASHER		BAKRUTESPOLARE		Group Grupp	
B											36	
C											Page Sida	
D											347	
E												
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R	
		A	B	C	D	E						
		1	-	-	-	-		Water reservoir	Vattenbehållare	SEE 36 • 343		
		1	-	-	-	-		Pump	Pump	SEE 36 • 343		
1	949931-0	X	-	-	-	-		Rubber hose by the meter	Gummislang metervara	LG 5100mm		2
2	1304460-7	1	-	-	-	-		Delivery valve	Tryckventil			2
3	949931-0	X	-	-	-	-		Rubber hose by the meter	Gummislang metervara	LG 1250mm		2
4	1258069-2	1	-	-	-	-		Grommet	Genomföring			3
5	1369535-8	1	-	-	-	-		Pipe elbow	Rörkrök			3
6	1347588-4	1	-	-	-	-		Strip clamp	Bandklamma			3
7	941268-5	1	-	-	-	-		Plug	Plugg			2
8	949931-0	X	-	-	-	-		Rubber hose by the meter	Gummislang metervara	LG 130mm		2
9	1369855-0	1	-	-	-	-		Washer jet	Spolarmunstycke			2
10	1304944-0	1	-	-	-	-		Connector	Skarvstycke			3
11	1304859-0	1	-	-	-	-		Retaining clip	Hållare			2