




VOLVO PARTS
1-980-29016
(107-6)

A							REPAIR PARTS, BODY SIDE		REPARATIONSDELAR, KAROSSIDA		Group Grupp	
B							81					
C							Page					
D							Sida					
E							881					
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R	
		A	B	C	D	E						
1	3526090-0	1	-	-	-	-		Body side, l.h.	Karossida, v	(1334989)	5	
	3526091-8	1	-	-	-	-		Body side, r.h.	Karossida, h	(1334990)	5	
2	1380145-1	1	-	-	-	-		• Cowl side, l.h.	• Torpedsida, v	1)	5	
	1380146-9	1	-	-	-	-		• Cowl side, r.h.	• Torpedsida, h	1)	5	
3	1380017-2	1	-	-	-	-		• B-pillar, l.h.	• B-stolpe, v	1)	3	
	1380018-0	1	-	-	-	-		• B-pillar, r.h.	• B-stolpe, h	1)	3	
4	1380019-8	1	-	-	-	-		• Rear pillar, l.h.	• Bakstolpe, v	1)	4	
	1380020-6	1	-	-	-	-		• Rear pillar, r.h.	• Bakstolpe, h	1)	4	
5	1380148-5	1	-	-	-	-		• Cant rail, l.h.	• Taksvällare, v	1)	4	
	1380150-1	1	-	-	-	-		• Cant rail, r.h.	• Taksvällare, h	1)	4	
6	1380023-0	1	-	-	-	-		• Bottom rail, l.h.	• Bottensvällare, v	1)	3	
	1380024-8	1	-	-	-	-		• Bottom rail, r.h.	• Bottensvällare, h	1)	3	
7	1355885-3	1	-	-	-	-		Mudguard repair part, l.h.	Skärmdel, v	1)	2	
	1355886-1	1	-	-	-	-		Mudguard repair part, r.h.	Skärmdel, h	1)	2	
8	3526117-1	1	-	-	-	-		Rear mudguard, l.h. l.h.	Bakskärm, v v	1) (1380133) 4DRS	2	
	3526118-9	1	-	-	-	-		Rear mudguard, r.h. r.h.	Bakskärm, h h	1) (1380134) 4DRS	2	

1) Service version. / Serviceutförande.