





VOLVO
Genuine Parts
PV 811 456 33

A							BODY SIDE INNER		KAROSSIDA INRE		Group Grupp
B											81
C											Page Sida
D											885
E							5DRS				
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	3526078-5	1	-	-	-	-		Cant rail, l.h.	Taksvällare, v	(1380151)	4
	3526079-3	1	-	-	-	-		Cant rail, r.h.	Taksvällare, h	(3526305)(1380152)	4
2	3526286-4	1	-	-	-	-		Windscreen pillar, l.h.	Vindrutestolpe, v	(1334991)	4
	3526286-4	1	-	-	-	-		Windscreen pillar, l.h.	Vindrutestolpe, v	CH 22304-	4
	3526287-2	1	-	-	-	-		Windscreen pillar, r.h.	Vindrutestolpe, h	(1334992)	4
3	3526080-1	1	-	-	-	-		B-pillar, l.h.	B-stolpe, v	(3526293)(3503396)	4
	3526081-9	1	-	-	-	-		B-pillar, r.h.	B-stolpe, h	(3526294)	4
4	3526328-4	1	-	-	-	-		Rear section, l.h.	Bakstycke, v	(3526300)	2
	1334179-7	1	-	-	-	-		Rear section, r.h.	Bakstycke, h	CH -APP 24799	2
	3526329-2	1	-	-	-	-		Rear section, r.h.	Bakstycke, h	(3526301) CH APP 24800-	2
5	1380844-9	1	-	-	-	-		Tie plate, l.h.	Knutplåt, v		5
	1380845-6	1	-	-	-	-		Tie plate, r.h.	Knutplåt, h		5
6	1355119-7	1	-	-	-	-		• Attaching lug	• Fästögla		4
7	1267673-0	1	-	-	-	-		Bracket, l.h.	Konsol, v		5
	1267674-8	1	-	-	-	-		Bracket, r.h.	Konsol, h		5