





VOLVO
Genuine Parts
PV 214 61874

							CHAIN TRANSMISSION		KEDJETRANSMISSION		Group Grupp
A											21
B											Page
C											Sida
D											149
E											
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1		1	-	-	-	-		Sprocket	Kedjedrev	SEE 21 • 147	
2		1	-	-	-	-		Sprocket	Kedjedrev	SEE 21 • 147	
3		1	-	-	-	-		Sprocket	Kedjedrev	SEE 22 • 177	
4		1	-	-	-	-		Sprocket	Kedjedrev	SEE 21 • 141	
5	245301-7	2	-	-	-	-		Chain	Kedja		2
6	245548-3	1	-	-	-	-		Chain	Kedja		3
6a	247531-7	2	-	-	-	-		Filter washer	Filterbricka	(1218036)	3
7	247282-7	2	-	-	-	-		Chain tensioner	Kedjesträckare		3
8	246065-7	2	-	-	-	-		Plate	Platta		4
9	955276-1	4	-	-	-	-		Screw	Skruv		2
10	941906-0	4	-	-	-	-		Spring washer	Fjäderbricka		2
11	246064-0	2	-	-	-	-		Spacer sleeve	Distanshylsa		4
12	947405-7	2	-	-	-	-		Screw	Skruv		2
13	948708-3	4	-	-	-	-		Washer	Bricka		2
14	247528-3	2	-	-	-	-		Slide strip	Glidlist		3
15	955271-2	4	-	-	-	-		Screw	Skruv	(955270)	2
16	941906-0	4	-	-	-	-		Spring washer	Fjäderbricka		2
17	955892-5	4	-	-	-	-		Washer	Bricka		2
18	247576-2	1	-	-	-	-		Seal	Tätning		2
19	1218307-5	1	-	-	-	-		Timing gear casing	Transmissionskåpa		4
20	1271485-3	1	-	-	-	-		Gasket	Packning		2
21	946480-1	4	-	-	-	-		Screw	Skruv	LG 25 mm	2
	946518-8	19	-	-	-	-		Screw	Skruv	LG 40 mm	2
	968318-6	1	-	-	-	-		Screw	Skruv	(947943) LG 55 mm	2
	948367-8	1	-	-	-	-		Screw	Skruv	LG 65 mm	2
	1218250-7	1	-	-	-	-		Screw	Skruv	LG 110 mm	5
22	946599-8	25	-	-	-	-		Spring washer	Fjäderbricka		2
23	1218409-9	4	-	-	-	-		Plug	Propp	(1218035)	3
24	1218239-0	1	-	-	-	-		Sealing ring	Tätningsring		2
25	271580-3	1	-	-	-	-		Repair kit	Reparationssats		2
								Chain	Kedja		