





A	1359649, 1359652					SERVO PUMP					SERVOPUMP					Group Grupp	
B																64	
C						SAGINAW					Page Sida						
D											817						
E																	
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R						
		A	B	C	D	E											
1	271311-3	1	-	-	-	-		Locating pin	Styrpinne		4						
2	3342655-2	1	-	-	-	-		Spring	Fjäder		3						
3	271310-5	1	-	-	-	-		Sleeve	Hylsa		4						
4	271312-1	1	-	-	-	-		Sealing ring	Tätningsring		2						
5	271314-7	1	-	-	-	-		Retaining ring	Spårring		3						
6	1272426-6	1	-	-	-	-		O-ring	O-ring		4						
7	271302-2	1	-	-	-	-		Rotor kit	Rotorsats		3						
8	271304-8	1	-	-	-	-		Repair kit	Reparationssats		3						
9	271305-5	1	-	-	-	-		Repair kit	Reparationssats		2						
10	3342651-1	1	-	-	-	-		Sealing kit	Tätningssats		2						
11	3342658-6	1	-	-	-	-		Repair kit	Reparationssats		3						
12	271313-9	1	-	-	-	-		Repair kit	Reparationssats		3						
13	271337-8	1	-	-	-	-		Valve kit	Ventilsats		3						