




VOLVO
Genuine Parts
PV 610 55853

A						REPAIR KITS BALL JOINT		REPARATIONSSATS KULLED		Group Grupp	
B										61	
C						Page					
D						Sida					
E						797					
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	270477-3	2	-	-	-	-		Ball joint kit	Kulledsats		2