




VOLVO
Genuine Parts
PV 370 49733

A							CABLE HARNESS ENGINE COMPARTMENT LEDNINGSMATTA MOTORRUM				Group Grupp
B											37
C											Page Sida
D											473
E							B280E, B280F				
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1	1363123-9	1	-	-	-	-		Cable harness	Ledningsmatta		5
2	1396094-3	1	-	-	-	-		Engine	Motor		5
	3515675-1	1	-	-	-	-		Cable harness, l.h.	Ledningsmatta, v	-1987	5
	3515778-3	1	-	-	-	-		Wheel housing	Hjulhus	1)	5
	3544101-3	1	-	-	-	-		Cable harness, l.h.	Ledningsmatta, v	2)	5
	1396099-2	1	-	-	-	-		Wheel housing	Hjulhus	-1990. (3515827)	5
	1396095-0	1	-	-	-	-		Cable harness, l.h.	Ledningsmatta, v	1991-	5
	3515117-4	1	-	-	-	-		Wheel housing	Hjulhus		5
	3515676-9	1	-	-	-	-		Cable harness, l.h.	Ledningsmatta, v	1) (J)	5
	3515626-4	1	-	-	-	-		Wheel housing	Hjulhus	1)	5
	1363623-8	1	-	-	-	-		Cable harness, r.h.	Ledningsmatta, h	2) -1989	5
	3515598-5	1	-	-	-	-		Wheel housing	Hjulhus		5
3	3523750-2	1	-	-	-	-		Cable harness, r.h.	Ledningsmatta, h	1990-	5
	3523750-2	1	-	-	-	-		Wheel housing	Hjulhus		5
	1396245-1	1	-	-	-	-		Cable harness	Ledningsmatta	-1987	5
		1	-	-	-	-	NS	Fuel pump	Bränslepump		5
		1	-	-	-	-		Cable harness	Ledningsmatta	(1363293), 1988-1990	5
		1	-	-	-	-		Fuel pump	Bränslepump		5
4	1396245-1	1	-	-	-	-		Cable harness	Ledningsmatta	1991-	5
		1	-	-	-	-		Fuel pump	Bränslepump		5
		1	-	-	-	-		Cable harness	Ledningsmatta	-1987	5
		1	-	-	-	-		Radiator fan	Kylarfläkt		5
		1	-	-	-	-		Cable harness	Ledningsmatta	1988-	5
		1	-	-	-	-		Radiator fan	Kylarfläkt		5
5	1363482-9	1	-	-	-	-		Cable harness	Ledningsmatta		5
6	948620-0	2	-	-	-	-		auxiliary light	extraljus		3
		2	-	-	-	-		Earth cable	Stomledning	LG 340mm	3
								Motor	Motor		
								Body	Kaross		

1) CH -6499.
2) CH 6793-