


1



VOLVO
Genuine Parts
PV 437 52822

A						GEARBOX COOLING		VÄXELLÅDSKYLNING			Group Grupp
B											43
C											Page Sida
D											677
E											
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1		1	-	-	-	-	NS	Gearbox cooling	Växellåds kylning		
2	1271540-5	1	-	-	-	-		• Tube	• Rör	(1274708)	3
3	1271490-3	1	-	-	-	-		• Tube	• Rör	(1274707)	3
4	954329-9	1	-	-	-	-		• Nipple	• Nippel		2
5	1274706-9	1	-	-	-	-		• Tube	• Rör	-1987	3
	1271512-4	1	-	-	-	-		• Tube	• Rör	1988-	3
6	1269581-3	1	-	-	-	-		• Tube	• Rör	-1987	3
	(1271511)	1	-	-	-	-	SP	• Tube	• Rör	1988-1989	3
										REPL 1PCS 3531570-4, 1PCS 1317841-3.	
7	3531570-4	1	-	-	-	-		• Oil pipe	• Oljerör	1990-	3
		1	-	-	-	-		• Nipple	• Nippel	-1989	
										SEE 26 • 293	
8	1317841-3	1	-	-	-	-		• Nipple	• Nippel	1990-	3
9	464402-7	1	-	-	-	-		• Connector	• Anslutning	SEE 43 • 657	
10	462996-0	1	-	-	-	-		• Bracket	• Konsol		3
11	948356-1	1	-	-	-	-		• Clamp	• Klamma		2
12	460428-6	3	-	-	-	-		• Flange screw	• Flänsskruv		2
13	1378342-8	1	-	-	-	-		• Clamp	• Klamma		2
14	945970-2	2	-	-	-	-		• Oil cooler	• Oljekylare		3
15	948871-9	2	-	-	-	-		• Screw	• Skruv		2
16	946655-8	X	-	-	-	-		• Spacer washer	• Distansbricka		2
								• Protecting hose	• Skyddsslang	ALTER	2