












VOLVO
Genuine Parts
PV 381 54561

A						ELECTRIC EQUIPMENT		ELUTRUSTNING		Group Grupp	
B										38	
C										Page Sida	
D										559	
E						ABS					
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R
		A	B	C	D	E					
1		1	-	-	-	-		Sensor rear	Givare bakre	SEE 46 • 693	
2	1324080-9	2	-	-	-	-		Sensor front	Givare främre	(1398781), -1987	2
	1363559-4	2	-	-	-	-		Sensor front	Givare främre	1)	2
	3515092-9	2	-	-	-	-		Sensor front	Givare främre	2)	2
3	1259854-6	2	-	-	-	-		Grommet	Genomföring	-1987	3
4	1273516-3	2	-	-	-	-		Rubber bushing	Gummibussning		2
5	942000-1	2	-	-	-	-		Screw	Skruv		2
6	1324786-1	1	-	-	-	-		Fuse box	Säkringsdosa	-1987	4
7	1323122-0	1	-	-	-	-		Fuse	Säkring	-1987, 80A	1
8	949480-8	2	-	-	-	-		Screw	Skruv	-1987	2
9	940090-4	2	-	-	-	-		Washer	Bricka	-1987	2
10	1324787-9	1	-	-	-	-		Cover	Lock	-1987	3
11	955127-6	2	-	-	-	-		Screw	Skruv		2
12		1	-	-	-	-		Control unit	Styrenhet	SEE 52 • 765	
13		1	-	-	-	-		Bracket	Konsol	SEE 52 • 765	
								Control unit	Styrenhet		
14	1324082-5	1	-	-	-	-		Overvoltage protector	Överspänningsskydd	-1987	3
15	969161-9	1	-	-	-	-		• Blade fuse	• Bladsäkring	(967545)	1
								Overvoltage protector	Överspänningsskydd	1988-	
										SEE 52 • 765	
16	1347928-2	1	-	-	-	-		Impulse converter	Impulsomvandlare	-1987	3
								Impulse converter	Impulsomvandlare	1988-	
										SEE 52 • 765	
17		1	-	-	-	-		Hydraulic unit	Hydraulenhhet	SEE 52 • 765	
18	1347895-3	1	-	-	-	-		• Relay	• Relä		2
								Motor	Motor		
								Pump	Pump		
19	1347896-1	1	-	-	-	-		• Relay	• Relä		2
								Valve	Ventil		
20	94081-7	2	-	-	-	-		Plug	Plugg		3
								Wheel housing	Hjulhus		
21	1348123-9	1	-	-	-	-		Grommet	Genomföring		5
								Sensor rear	Givare bakre		
22	1347305-3	4	-	-	-	-		Clip	Clips		3
23	3515144-8	2	-	-	-	-		Clip	Clips		2
								Wheel housing	Hjulhus		
24	3515144-8	1	-	-	-	-		Clip	Clips		2
								Engine compartment	Motorrum		
25	1387273-4	2	-	-	-	-		Dust cap	Dammskydd		4
26	955992-3	2	-	-	-	-		O-ring	O-ring		6

1) CH -6499.

2) CH 6793-